

# NovaChem Chemicals Pvt. Ltd.

## NovaChem Industrial Plant

Plot No. 18, GIDC Industrial Estate,  
Vadodara, Gujarat - 390010

### Instrument Calibration Report

#### Document Information

|                 |                   |
|-----------------|-------------------|
| Document UUID   | DB14F87B          |
| Document Number | CAL_EVT-056       |
| Event ID        | EVT-056           |
| Chain ID        | CH-019            |
| Equipment ID    | M-101             |
| Department      | Quality           |
| Generated On    | 15-Jul-2026 14:12 |
| Confidentiality | Internal Use Only |

#### Document Control

|                 |             |
|-----------------|-------------|
| Document Number | CAL_EVT-056 |
| Issue Date      | 20-Jun-2026 |
| Revision        | Rev-1.0     |
| Prepared By     | Pooja Mehta |
| Approved By     | Neha Singh  |
| Status          | Approved    |

#### Calibration Information

|                     |             |
|---------------------|-------------|
| Calibration Number  | CAL_-056    |
| Event ID            | EVT-056     |
| Equipment ID        | M-101       |
| Instrument Name     | Agitator    |
| Department          | Quality     |
| Assigned Technician | Pooja Mehta |
| Status              | Closed      |

#### Equipment Details

|                |              |
|----------------|--------------|
| Equipment ID   | M-101        |
| Equipment Name | Agitator     |
| Area           | Reactor Area |

|                   |                |
|-------------------|----------------|
| Department        | Quality        |
| Shift             | Evening        |
| Reported From     | Utilities Area |
| Asset Criticality | High           |
| Failure Category  | Mechanical     |
| Downtime          | 3 Hours        |

Calibration Objective

Calibration check performed for:

M-101

Purpose was to verify instrument accuracy and detect measurement deviation.

Calibration Findings

Calibration findings:

Equipment:

Agitator

Observed Condition:

Leakage detected

Deviation Analysis

Calibration deviation identified.

Possible Cause:

Seal failure

## Adjustment Performed

Adjustment performed.

Corrective Action:

Seal replaced

## Calibration Verification

Post-adjustment verification completed.

Instrument accuracy restored successfully.

## Previous Equipment History

| Event   | Date       | Failure          | Status |
|---------|------------|------------------|--------|
| EVT-026 | 2026-03-22 | Bearing wear     | Closed |
| EVT-041 | 2026-05-06 | Routine schedule | Closed |
| EVT-056 | 2026-06-20 | Seal failure     | Closed |

## Calibration Checklist

- ☒ Lock Out / Tag Out (LOTO) Followed
- ☒ PPE Worn
- ☒ Visual Inspection Completed
- ☒ Lubrication Checked
- ☒ Leak Inspection Completed
- ☒ Alignment Verified
- ☒ Trial Run Successful

## Recommendations

Conduct thermography inspection next month.

## Linked Documents

- WO\_EVT-056.docx
- MNT\_EVT-056.docx
- INS\_EVT-056.docx
- EMAIL\_EVT-056.txt

## Approval

|             |             |
|-------------|-------------|
| Prepared By | Pooja Mehta |
| Approved By | Neha Singh  |