

# NovaChem Chemicals Pvt. Ltd.

## NovaChem Industrial Plant

Plot No. 18, GIDC Industrial Estate,  
Vadodara, Gujarat - 390010

### Safety Incident Investigation

#### Document Information

|                 |                   |
|-----------------|-------------------|
| Document UUID   | 5081B37B          |
| Document Number | SAF_EVT-022       |
| Event ID        | EVT-022           |
| Chain ID        | CH-008            |
| Equipment ID    | CT-101            |
| Department      | Engineering       |
| Generated On    | 15-Jul-2026 14:01 |
| Confidentiality | Internal Use Only |

#### Document Control

|                 |              |
|-----------------|--------------|
| Document Number | SAF_EVT-022  |
| Issue Date      | 10-Mar-2026  |
| Revision        | Rev-1.0      |
| Prepared By     | Rahul Sharma |
| Approved By     | Amit Verma   |
| Status          | Approved     |

#### Safety Information

|                      |                |
|----------------------|----------------|
| Safety Report Number | SAF_-022       |
| Event ID             | EVT-022        |
| Department           | Engineering    |
| Area                 | Utility        |
| Shift                | Morning        |
| Reported By          | Utilities Area |
| Severity             | High           |
| Status               | Closed         |

#### Equipment Details

|                |               |
|----------------|---------------|
| Equipment ID   | CT-101        |
| Equipment Name | Cooling Tower |

|                   |                 |
|-------------------|-----------------|
| Area              | Utility         |
| Department        | Engineering     |
| Shift             | Morning         |
| Reported From     | Utilities Area  |
| Asset Criticality | Medium          |
| Failure Category  | Instrumentation |
| Downtime          | 6 Hours         |

Safety Event Description

Safety incident occurred during:

Morning shift.

Incident Details:

Minor spill

Hazard Identification

Hazard category:

Instrumentation

Root Cause:

Loose flange

Risk Assessment

Risk Priority:

Low

Severity:

High

## Immediate Action Taken

Immediate corrective action:

Flange tightened

## Root Cause Analysis

Loose flange

## Corrective Action

Flange tightened

## Preventive Action

Provide safety awareness training  
and improve preventive monitoring.

## Safety Officer Remarks

Operator advised to monitor pressure readings for 48 hours.

## Safety Compliance Checklist

☒ Lock Out / Tag Out (LOTO) Followed

☒ PPE Worn

☒ Visual Inspection Completed

☒ Lubrication Checked

☒ Leak Inspection Completed

☒ Alignment Verified

☒ Trial Run Successful

Previous Equipment History

|         |            |              |        |
|---------|------------|--------------|--------|
| Event   | Date       | Failure      | Status |
| EVT-022 | 2026-03-10 | Loose flange | Closed |

Recommendations

Conduct thermography inspection next month.

Linked Documents

- WO\_EVT-022.docx
- MNT\_EVT-022.docx
- INS\_EVT-022.docx
- EMAIL\_EVT-022.txt

Approval

|             |              |
|-------------|--------------|
| Prepared By | Rahul Sharma |
| Approved By | Amit Verma   |