

# NovaChem Chemicals Pvt. Ltd.

## NovaChem Industrial Plant

Plot No. 18, GIDC Industrial Estate,  
Vadodara, Gujarat - 390010

### Safety Incident Investigation

#### Document Information

|                 |                   |
|-----------------|-------------------|
| Document UUID   | BB97641C          |
| Document Number | SAF_EVT-033       |
| Event ID        | EVT-033           |
| Chain ID        | CH-011            |
| Equipment ID    | R-101             |
| Department      | Inspection        |
| Generated On    | 15-Jul-2026 14:01 |
| Confidentiality | Internal Use Only |

#### Document Control

|                 |              |
|-----------------|--------------|
| Document Number | SAF_EVT-033  |
| Issue Date      | 12-Apr-2026  |
| Revision        | Rev-1.0      |
| Prepared By     | Neha Singh   |
| Approved By     | Anjali Desai |
| Status          | Approved     |

#### Safety Information

|                      |              |
|----------------------|--------------|
| Safety Report Number | SAF_-033     |
| Event ID             | EVT-033      |
| Department           | Inspection   |
| Area                 | Reactor Area |
| Shift                | Night        |
| Reported By          | Tank Farm    |
| Severity             | Medium       |
| Status               | Closed       |

#### Equipment Details

|                |                  |
|----------------|------------------|
| Equipment ID   | R-101            |
| Equipment Name | Chemical Reactor |

|                   |                 |
|-------------------|-----------------|
| Area              | Reactor Area    |
| Department        | Inspection      |
| Shift             | Night           |
| Reported From     | Tank Farm       |
| Asset Criticality | Critical        |
| Failure Category  | Instrumentation |
| Downtime          | 4 Hours         |

## Safety Event Description

Safety incident occurred during:

Night shift.

Incident Details:

Routine PM

## Hazard Identification

Hazard category:

Instrumentation

Root Cause:

Routine schedule

## Risk Assessment

Risk Priority:

Medium

Severity:

Medium

## Immediate Action Taken

Immediate corrective action:

Serviced

## Root Cause Analysis

Routine schedule

## Corrective Action

Serviced

## Preventive Action

Provide safety awareness training  
and improve preventive monitoring.

## Safety Officer Remarks

Preventive maintenance interval should be reduced.

## Safety Compliance Checklist

☒ Lock Out / Tag Out (LOTO) Followed

☒ PPE Worn

☒ Visual Inspection Completed

☒ Lubrication Checked

☒ Leak Inspection Completed

☒ Alignment Verified

☒ Trial Run Successful

## Previous Equipment History

| Event   | Date       | Failure          | Status |
|---------|------------|------------------|--------|
| EVT-006 | 2026-01-21 | Control tuning   | Closed |
| EVT-007 | 2026-01-24 | Routine          | Closed |
| EVT-008 | 2026-01-27 | Follow-up        | Closed |
| EVT-009 | 2026-01-30 | Bearing wear     | Closed |
| EVT-010 | 2026-02-02 | Follow-up        | Closed |
| EVT-018 | 2026-02-26 | Bearing wear     | Closed |
| EVT-033 | 2026-04-12 | Routine schedule | Closed |

## Recommendations

Perform vibration analysis after one week.

## Linked Documents

- WO\_EVT-033.docx
- MNT\_EVT-033.docx
- INS\_EVT-033.docx
- EMAIL\_EVT-033.txt

## Approval

|             |              |
|-------------|--------------|
| Prepared By | Neha Singh   |
| Approved By | Anjali Desai |