

# NovaChem Chemicals Pvt. Ltd.

## NovaChem Industrial Plant

Plot No. 18, GIDC Industrial Estate,  
Vadodara, Gujarat - 390010

### Safety Observation Report

#### Document Information

|                 |                   |
|-----------------|-------------------|
| Document UUID   | A3391972          |
| Document Number | SAF_EVT-056       |
| Event ID        | EVT-056           |
| Chain ID        | CH-019            |
| Equipment ID    | M-101             |
| Department      | Quality           |
| Generated On    | 15-Jul-2026 14:01 |
| Confidentiality | Internal Use Only |

#### Document Control

|                 |             |
|-----------------|-------------|
| Document Number | SAF_EVT-056 |
| Issue Date      | 20-Jun-2026 |
| Revision        | Rev-1.0     |
| Prepared By     | Pooja Mehta |
| Approved By     | Neha Singh  |
| Status          | Approved    |

#### Safety Information

|                      |                |
|----------------------|----------------|
| Safety Report Number | SAF_-056       |
| Event ID             | EVT-056        |
| Department           | Quality        |
| Area                 | Reactor Area   |
| Shift                | Evening        |
| Reported By          | Utilities Area |
| Severity             | Medium         |
| Status               | Closed         |

#### Equipment Details

|                |          |
|----------------|----------|
| Equipment ID   | M-101    |
| Equipment Name | Agitator |

|                   |                |
|-------------------|----------------|
| Area              | Reactor Area   |
| Department        | Quality        |
| Shift             | Evening        |
| Reported From     | Utilities Area |
| Asset Criticality | High           |
| Failure Category  | Mechanical     |
| Downtime          | 3 Hours        |

Safety Event Description

Safety observation recorded for:

Equipment Name:  
Agitator

Observation:

Leakage detected

Hazard Identification

Potential hazard identified:

Failure Category:

Mechanical

Severity:

Medium

Risk Assessment

Risk Level:

Medium

Asset Criticality:

High

## Immediate Action Taken

Immediate action taken:

Seal replaced

## Root Cause Analysis

Seal failure

## Corrective Action

Seal replaced

## Preventive Action

Conduct regular safety inspections  
and ensure compliance with safety procedures.

## Safety Officer Remarks

No abnormal noise observed after trial run.

## Safety Compliance Checklist

☒ Lock Out / Tag Out (LOTO) Followed

☒ PPE Worn

☒ Visual Inspection Completed

☒ Lubrication Checked

☒ Leak Inspection Completed

☒ Alignment Verified

☒ Trial Run Successful

## Previous Equipment History

| Event   | Date       | Failure          | Status |
|---------|------------|------------------|--------|
| EVT-026 | 2026-03-22 | Bearing wear     | Closed |
| EVT-041 | 2026-05-06 | Routine schedule | Closed |
| EVT-056 | 2026-06-20 | Seal failure     | Closed |

## Recommendations

Check lubrication schedule.

## Linked Documents

- WO\_EVT-056.docx
- MNT\_EVT-056.docx
- INS\_EVT-056.docx
- EMAIL\_EVT-056.txt

## Approval

|             |             |
|-------------|-------------|
| Prepared By | Pooja Mehta |
| Approved By | Neha Singh  |