

MCAS mis-activation on faulty design



0.01*0.99+0.01*0.99+0.01*0.01=1.99% or 0.01*0.98+0.01*0.98+0.01*0.01=1.97%

MCAS mis-activation on aggressive design


10(图) +5 (计算)



0.01*0.01=0.01%


MCAS activation failure on faulty design

10(图) +5 (计算)




0.01*0.01=0.01%

MCAS activation failure on aggressive design




0.01*0.99+0.01*0.99+0.01*0.01=1.99% or 0.01*0.98+0.01*0.98+0.01*0.01=1.97%

MCAS activation on 2/3 design



MCAS activation failure on 2/3 design



0.01*0.01*0.99*3+0.01*0.01*0.01=0.0298% or 0.0295%

Result summary

	Faulty	Aggressive	2/3
MCAS mis-activation	1.97%/1.99%	0.01%	0.0298%/0.0295%
MCAS fails to activate when needed	0.01%	1.97%/1.99%	0.0298%/0.0295%