

Total No. of Questions : 8]

[Total No. of Printed Pages : 3

Roll No

AU/ME-4003-CBGS

B.E. IV Semester

Examination, June 2020

Choice Based Grading System (CBGS)
Machine Drawing and CAD

Time : Three Hours

Maximum Marks : 70

- Note:** i) Attempt any four questions.
ii) Question No. 3 is compulsory.

1. Sketch the following welding symbol along with respective illustration. 14
 - a) Single V-butt weld
 - b) Single U-butt weld
 - c) Square butt weld
 - d) Filled weld
2.
 - a) Draw any five conventional representations of machines components. 7
 - b) Sketch any two types of structural riveted, indicating proportionate dimensions. 7
3. Assemble all the parts of pedestal bearing and draw front view in full in section and top view. Also mention bill of material. Details are given in fig.1. 28
4. What is meant by edit functions in drafting. List down commonly used 5 edit functions giving their uses. 14

AU/ME-4003-CBGS

PTO

[2]

5. What are the commands used in 3D models and explain any two. 14
6. a) What do you mean by Snap and Grid? Describe their use. 7
b) What is the purpose of OFFSET command? Draw a figure to show its use. 7
7. a) Draw sectional front view and top view for a double riveted butt joint for plates of thickness 9mm with double cover plate and zig-zag riveting. 7
b) Differentiate between the following types of threads: 7
i) Metric and BSW
ii) Square and Acme
iii) Pitch and lead of thread
8. Write short note on (any two) 14
i) Sectioning and section view
ii) Representation of welded joints
iii) Basic concepts of assembly drawing
iv) Different types of threaded fasteners

[3]




Figure 1
