

Total No. of Questions : 8]

[Total No. of Printed Pages : 1

Roll No

TX-802 (GS)
B.E. VIII Semester Examination, June 2020
Grading System (GS)
Process Control in Spinning and Weaving
Time : Three Hours

Maximum Marks : 70

- Note:** i) Attempt any five questions.
ii) All questions carry equal marks.

1. Explain the various types of fabric faults, their causes and remedies.
2. If a ring frame of 1200 spindles producing Ne 20 combed warp yarn and the total end breaks in one doff is 60. Calculate the end breaks/100spd/hr if full cop is prepared in 120 min.
3. Explain 14 Fabric defects with their cause and remedies.
4. What is yarn realization? Assume approximate yarn realisation of Ne 30^s combed Hosiery yarn with proper justification of data.
5. a) What is hard waste? Comment on “Hard waste is direct loss to production”.
b) Mention 14 process check points in sizing and weaving.
6. Illustrate the method of ‘Process standardization’ with the help of a flow-chart.
7. Calculate the efficiency of weaving machine if the time to mend a broken end is 60 sec, time to change the cloth beam is 1200 sec, time to change a weaver beam is 3000 sec, total breaks per hour is 15, total running time is 8 hrs, total cloth beam change is 2 and total weaver beam change is 0.5. (Assume necessary data if required)
8. Write short notes on:
 - i) Control of yarn count in spinning.
 - ii) Importance of snap study with two examples.
 - iii) Control in hard waste in winding.
