
## Motor Control Logic

Good get every motor to B simultaneously charget angle

Co Given. Accel Stepper Pobrary




Gruno poll motor and stepleturn true it step due

6 moveTo: set target pos

set Speed: set man speed (run function will attempt to accelerate to this speed)

65 setAcceleration: set acceleration rate (expensive call and avoid it possible)



Shaff

Stepper motor