(From the register file's two write ports) WDestO NDest Resolve or Kill JUOP Code BrMask Ctrl... RDst RS1 RS2 p2 ready request ready issue slot is valid issue Issue Select Logic Physical Physical Source Control Signals Destination Registers Register Issued to the Register Read stage