POID-4523310336

Dhruvit | Aug 12, 2026, 12:52 PM

Table of content

Job details

LT_Mini_Pillar — Dhruvit | Aug 12, 2026, 12:52 PM

Job details

Job Id	Start Date	End Date	Category	Asset	Site	Description
PH2026100003	-	-	LT	-	IIM Ahmedabad	-

Table of content

Inspection details

Basic Details **(Page complete: 100%)**

- Basic Details **(Inspection Points: 8/8)**

Characteristics _ Parameter **(Page complete: 100%)**

- Visual & Physical Checks **(Inspection Points: 11/11)**
- BOM Verification **(Inspection Points: 1/1)**
- Fabrication & Manufacturing Quality Checks **(Inspection Points: 2/2)**
- Raw Material / Bought out Items TC Verification **(Inspection Points: 2/2)**
- Photos Upload **(Inspection Points: 3/3)**
- Acceptance Tests as per QAP/IS **(Inspection Points: 4/4)**
- Other Compliances for Manufacturing Facility **(Inspection Points: 5/5)**

Inspection Observations **(Page complete: 100%)**

- Default **(Inspection Points: 3/3)**

Inspection Conclusion **(Page complete: 100%)**

- Inspection Summary **(Inspection Points: 3/3)**

Inspection details

Prepared by	Started on	Category	Sub category	Description	Inspection location
Dhruvit	Aug 12, 2026, 12:52 PM	LT	Mini Pillar	-	0, 0

Status

Completed

Basic Details

Page complete: 100%

Basic Details

Inspection Points: 8/8

Title : SAP Code

Answer 10461550

Title : Vendor Name

Answer ABB India Limited

Title : Offered Qty

Answer 50 Nos

Title : PO Details

Answer
PO No. 4500137890 dated 20-Jul-2026

Title : AEML Engineer & Designation

Answer
Rajesh Sharma, Senior Engineer (QA)

Title : Vendor Engineer & Designation

Answer
Suresh Iyer, Production In-charge

Title : Sl Nos of Items

Answer

LTMP/2026/0501 to LTMP/2026/0525

Title : Date of Inspection

Answer — Aug 12, 2026

Characteristics _ Parameter

Page complete: 100%

Visual & Physical Checks

Inspection Points: 11/11

Title : Dimensions

Input — Ok

Note : Overall H×W×D verified on 3 samples — OK.

Title : Sheet Steel Thickness & Type

Input — Canopy -3mm

Note : Body sheet below 2 mm at side panel — Not OK.

Title : Electrical Clearances

Input — Ok

Title : Earthing

Input — Ok

Title : Paint Shade & Thickness

Input — Ok

Title : Gland Plate- Hole Size and Knockouts

Input — Ok

Title : Hardware

Input — Ok

Title : Door Hinges /Interlock for door removal from hinge

Input Not Ok

Title : Locking Arrangement

Input Ok

Title : Danger Boards

Input Not Ok

Note : Danger board loose on two units; re-fixed during visit.

Title : Foundation Structure

Input Not Ok

Note : Bolt hole pitch off by ~5 mm — civil mismatch.

BOM Verification

Inspection Points: 1/1

Title : Bill of Material

Input Not Ok

Note : No BOM deviation vs approved revision.

Fabrication & Manufacturing Quality Checks

Inspection Points: 2/2

Title : Welding

Input Not Ok

Title : Finishing & Painting

Input Not Ok

Raw Material / Bought out Items TC Verification

Inspection Points: 2/2

Title : TC of GI sheet from raw material sub vendor

Input Not Ok

Title : Bus Bar Conductivity

Input — Not Ok

Photos Upload

Inspection Points: 3/3

Title : All 4 sides view with door closed condition

Input — Not Attached

Title : Door Open Views Front & Back

Input — Attached

Title : Foundation Structure View

Input — Attached

Acceptance Tests as per QAP/IS

Inspection Points: 4/4

Title : Insulation resistance test phase to phase & phase to earth

Input — Ok

Title : High voltage test

Input — Ok

Note : Passed as per QAP acceptance criteria.

Title : Powder coating thickness measurement

Input — Not Ok

Title : Al Bus Bar conductivity measurement

Input — Not Ok

Note : Measured value outside acceptance band.

Other Compliances for Manufacturing Facility

Inspection Points: 5/5

Title : Safety Aspects in Facility

Input — Ok

Note : No unsafe condition noted during walk-through.

Title : House Keeping

Input — Not Ok

Note : Oil spills near packing bay; slip hazard noted.

Title : Eco-friendly Waste Segregation, Collection and Storage Practices w.r.t Hazardous / Non-Hazardous Materials

Input — Ok

Title : Calibration of Testing Instruments

Input — Not Ok

Title : SA 8000 Compliance

Input — Not Ok

Inspection Observations

Page complete: 100%

Default

Inspection Points: 3/3

Observations : 1.

Answer
Gland plate knockout sizes verified against cable schedule; one spare knockout to be blanked before dispatch.

Observations : 2

Answer
Danger board fixing found loose on two units; re-fixed with spring washers and verified.

Observations : 3

Answer
Foundation bolt hole pitch matches approved civil drawing; no rework required.

Inspection Conclusion

Page complete: 100%

Inspection Summary

Inspection Points: 3/3

Title : Test Results

Answer

Not Ok

Title : Technical Clearance

Answer

Yes

Title : Declaration

Answer

Re-inspection will be required after rectification of the non-conformances listed in observations. Present lot is not clea red for dispatch.