POID-4593151822

Dhruvit | Aug 12, 2026, 02:42 PM

Table of content

Job details

LT_Mini_Pillar — Dhruvit | Aug 12, 2026, 02:42 PM

Job details

Job Id	Start Date	End Date	Category	Asset	Site	Description
PH2026100009	-	-	LT	-	IIM Ahmedabad	-

Table of content

Inspection details

Basic Details **(Page complete: 100%)**

- Basic Details **(Inspection Points: 8/8)**

Characteristics _ Parameter **(Page complete: 100%)**

- Visual & Physical Checks **(Inspection Points: 11/11)**
- BOM Verification **(Inspection Points: 1/1)**
- Fabrication & Manufacturing Quality Checks **(Inspection Points: 2/2)**
- Raw Material / Bought out Items TC Verification **(Inspection Points: 2/2)**
- Photos Upload **(Inspection Points: 3/3)**
- Acceptance Tests as per QAP/IS **(Inspection Points: 4/4)**
- Other Compliances for Manufacturing Facility **(Inspection Points: 5/5)**

Inspection Observations **(Page complete: 100%)**

- Default **(Inspection Points: 3/3)**

Inspection Conclusion **(Page complete: 100%)**

- Inspection Summary **(Inspection Points: 3/3)**

Inspection details

Prepared by	Started on	Category	Sub category	Description	Inspection location
Dhruvit	Aug 12, 2026, 02:42 PM	LT	Mini Pillar	-	0, 0

Status

Completed

Basic Details

Page complete: 100%

Basic Details

Inspection Points: 8/8

Title : SAP Code

Answer: 10460112

Title : Vendor Name

Answer: ABB India Limited

Title : Offered Qty

Answer: 50 Nos

Title : PO Details

Answer
PO No. 4500137890 dated 20-Jul-2026

Title : AEML Engineer & Designation

Answer
Rajesh Sharma, Senior Engineer (QA)

Title : Vendor Engineer & Designation

Answer: Amit Verma, Quality Engineer

Title : Sl Nos of Items

Answer
LTMP/2026/0501 to LTMP/2026/0525

Title : Date of Inspection

Answer — Aug 12, 2026

Characteristics _ Parameter

Page complete: 100%

Visual & Physical Checks

Inspection Points: 11/11

Title : Dimensions

Input — Not Ok

Title : Sheet Steel Thickness & Type

Input — Canopy -3mm Not OK

Note : Canopy measured 2.6 mm at front edge (spec 3 mm).

Title : Electrical Clearances

Input — Not Ok

Note : Phase–earth clearance short near bus support insulator.

Title : Earthing

Input — Not Ok

Title : Paint Shade & Thickness

Input — Not Ok

Title : Gland Plate- Hole Size and Knockouts

Input — Not Ok

Title : Hardware

Input — Not Ok

Title : Door Hinges /Interlock for door removal from hinge

Input — Not Ok

Note : Interlock stiff / jammed on sample; adjusted pending recheck.

Title : Locking Arrangement

Input — Not Ok

Title : Danger Boards

Input — Not Ok

Title : Foundation Structure

Input — Not Ok

BOM Verification

Inspection Points: 1/1

Title : Bill of Material

Input — Not Ok

Note : Bus support insulator qty short vs BOM.

Fabrication & Manufacturing Quality Checks

Inspection Points: 2/2

Title : Welding

Input — Not Ok

Title : Finishing & Painting

Input — Not Ok

Raw Material / Bought out Items TC Verification

Inspection Points: 2/2

Title : TC of GI sheet from raw material sub vendor

Input — Not Ok

Note : Sub-vendor TC expired / not available for offered lot.

Title : Bus Bar Conductivity

Input — Not Ok

Photos Upload

Inspection Points: 3/3

Title : All 4 sides view with door closed condition

Input — Not Attached

Title : Door Open Views Front & Back

Input — Not Attached

Title : Foundation Structure View

Input — Not Attached

Acceptance Tests as per QAP/IS

Inspection Points: 4/4

Title : Insulation resistance test phase to phase & phase to earth

Input — Not Ok

Title : High voltage test

Input — Not Ok

Title : Powder coating thickness measurement

Input — Not Ok

Title : Al Bus Bar conductivity measurement

Input — Not Ok

Other Compliances for Manufacturing Facility

Inspection Points: 5/5

Title : Safety Aspects in Facility

Input — Not Ok

Note : Welding without screen in open bay — safety observation.

Title : House Keeping

Input — Not Ok

Note : Scrap mixed with finished goods staging — improve HK.

Title : Eco-friendly Waste Segregation, Collection and Storage Practices w.r.t Hazardous / Non-Hazardous Materials

Input — Not Ok

Title : Calibration of Testing Instruments

Input — Not Ok

Note : DFT gauge calibration overdue by 15 days.

Title : SA 8000 Compliance

Input — Not Ok

Inspection Observations

Page complete: 100%

Default

Inspection Points: 3/3

Observations : 1.

Answer
Welding undercut at bottom channel joint; dye-penetrant check failed — repair pending.

Observations : 2

Answer
Danger board missing / loosely fixed on multiple units; safety non-conformance.

Observations : 3

Answer
Bus bar conductivity out of specified limit on sample; TC mismatch under review.

Inspection Conclusion

Page complete: 100%

Inspection Summary

Inspection Points: 3/3

Title : Test Results

Answer

Not Ok

Note : Lot not meeting QAP acceptance criteria.

Title : Technical Clearance

Answer

Rejected

Title : Declaration

Answer

Acceptance tests / visual checks not meeting specification. Material is rejected for the offered lot.