Relay switching to switch between different to input XLR to one XLR and SE outputs

Signal inputs

1725669 J16: inp_1_bal_R_- / sig ground / inp_1_bal_R_+

1725669 J15: inp_1_bal_L_- / sig ground / inp_1_bal_L_+

1725669 J14: inp_2_bal_R_- / sig ground / inp_2_bal_R_+

1725669 J13: inp_2_bal_L_- / sig ground / inp_2_bal_L_+

Signal inputs

1725669 J10: SE_1_L / sig ground / SE_1_R

1725669 J12: SE_2_L / sig ground / SE_2_R

Switching

Right Balanced switch

+5V, inp_1_bal_R_-, inp_2_bal_R_-, inp_1_bal_R_+, inp_2_bal_R_+ → EC2-5SNU K2 → switch power, out_R_-, sig ground, out_R_+ → out balanced Right → 1725669 J17

Left Balanced switch

+5V, inp_1_bal_L_-, inp_2_bal_L_-, inp_1_bal_L_+, inp_2_bal_L_+ → EC2-5SNU K1 → switch power, out_L_-, sig ground, out_L_+ → out balanced Left → 1725669 J18

SIGNAL OUTPUTS

SE Balanced switch

+5V, SE_1_L, SE_2_L, SE_1_R, SE_2_R → EC2-5SNU K3 → switch power, SE_OUT_L, sig ground, SE_OUT_R → Single ended out → 1725669 J19

Power

5v DC power

switch power

all lines switched togather, unless testing

IC1 ULN2003LVDR (IN1–IN7, GND; OUT1–OUT7, COM)

D2, R2 1k

J1 1725669 — GND2

C1 0.1

PWR_FLAG

J3 1725669 — +5V

D1, R1 1k

sig ground

PWR_FLAG, R3 10R, PWR_FLAG → GND2

GND2

J2 Conn_01x01_Socket — Earth

SIGNAL CONTROL

H1 MountingHole
H2 MountingHole
H3 MountingHole
H4 MountingHole

Sheet: /
File: Relay OUT Signal switch board.kicad_sch

Title:

Size: A4 | Date: 2024-12-06 | **Rev: v1.0**
KiCad E.D.A. 10.0.6 | Id: 1/1