



NOTES:
UNLESS OTHERWISE SPECIFIED:
1. ALL DIMENSIONS IN MM
2. TOLERANCES:
X.X=±.5
ANGLES=±1°
3. INSIDE TOOL RADIUS .02 MAX
4. BREAK SHARP EDGES .01 MAX
5. ✓ FAO