



NOTES:  
UNLESS OTHERWISE SPECIFIED:  
1. ALL DIMENSIONS IN MM  
2. TOLERANCES:  
X.X=±.5  
ANGLES=±1°  
3. INSIDE TOOL RADIUS .02 MAX  
4. BREAK SHARP EDGES .01 MAX  
5. ✓ FAO