






**OPTIMIZE THE WEAR OF YOUR CRUSHERS** 

An accurate feed-rate enhances the productivity of your plant while reducing the operational costs









	2	4	å	
Model	ТРН	kW	Kg	Un
FD-AVA 800	200	11	4500	8
FD-AVA 1000	300	15	7200	8
FD-AVA 1200	500	18,5	10000	8
FD-AVA 1500	700	30	14000	12
FD-AVA 1800	1200	45	17000	12
_			Springs	







	2	4	å	<b>©</b>
Model	ТРН	kW	Kg	Un
FD-AVM 40x80	80	0,6	124	2
FD-AVM 50x90	120	1,1	150	2
FD-AVM 60x105	150	1,1	205	2
FD-AVM 70x120	200	1,1	210	2
FD-AVM 80x135	250	1,2	284	2
FD-AVM 90x150	300	1,2	352	2
FD-AVM 110x180	400	3,7	485	2
2 Pro	duction <b>7</b> Powe	er 🔔 Weight	Motovibrators	



