
naive cert.
full cert.
deployed R2
n/a
accepts
(a) $K_m = 1$
accepts
refuses
(b) $b_B = 2$
accepts
refuses
(c) single rate
(simulated at $T_s = 0.2$)
n/a
refuses
(e) $\varepsilon_{\text{adv}} = 1$
n/a
refuses
0/16
4/16
9/16
10/16
16/16
0
10
20
seeds leaving the safe set
(of 16, full-order plant)
+2.1e-06
-0.025
-0.042
-0.16
-0.026
−0.2
−0.1
0.0
$\min_t h(x(t))$ over seeds
(full-order plant)