

APEX COLLISION REPAIR ESTIMATE

Estimate ID: EST-2026-9874	Date: May 26, 2026
Vehicle: 2021 Toyota Camry LE	Claim No: CLM-99120
Owner: John Doe	Odometer: 45,210 mi

Repair Line Items

Line	Operation	Description	Part Number	Qty	Unit Price	Labor Hrs	Total (\$)
1	Replace	Rear Bumper Cover	52159-06950	1	345.00	2.5	345.00
2	Paint	Rear Bumper Cover	N/A	1	0.00	3.0	0.00
3	Refinish	Rear Bumper Cover (Overlapping paint operations)	N/A	1	120.00	2.0	120.00
4	Replace	Rear Tail Light Assembly Left	81560-06850	1	185.00	0.8	185.00
5	Replace	Front Bumper Cover (Unrelated to Rear impact)	52119-06A20	1	380.00	2.2	380.00
6	Replace	Front Grille (Unrelated to Rear impact)	53101-06510	1	150.00	1.0	150.00
7	Repair	Rear Quarter Panel Left	N/A	1	0.00	4.5	0.00
8	Paint	Rear Quarter Panel Left	N/A	1	0.00	2.5	0.00

Parts Total:	\$1,060.00
Labor Total (15.0 hrs @ \$60/hr):	\$900.00
Tax / Refinish Supplies:	\$180.00
Grand Total:	\$2,140.00