

Guidelines for Dealing With Product Non-Conformity under BIS Conformity Assessment.

1. Classification of non-conformities (critical / major / minor).
2. Containment and root-cause analysis.
3. Corrective action and verification by BIS officer.
4. Records to be retained at the factory for audit.

This prototype PDF is longer so the admin warehouse viewer has readable pages.