



Enforcement / Inspection Case Directory

This enforcement directory is a synthetic demonstration dataset for BIS MITRA. All identifiers, organizations, locations, test references, notices, orders and case outcomes are fictional. The records are structured to support retrieval, source citation, filtering and follow-up questions.

Demo Id	Inspection Date	Inspection Type	Severity	Case Status
ENF-DEMO-001	2026-09-26	Market Inspection	High	Pending Corrective Action
ENF-DEMO-002	2026-09-26	Factory Inspection	High	Active
ENF-DEMO-003	2026-09-26	Market Inspection	High	Under Investigation
ENF-DEMO-004	2026-09-24	Factory Inspection	Medium	Pending Corrective Action
ENF-DEMO-005	2026-09-23	Market Inspection	Medium	Active
ENF-DEMO-006	2026-09-22	Factory Inspection	Critical	Active
ENF-DEMO-007	2026-09-20	Market Inspection	Low	Closed
ENF-DEMO-008	2026-09-18	Factory Inspection	Medium	Closed
ENF-DEMO-009	2026-09-17	Market Inspection	High	Under Investigation
ENF-DEMO-010	2026-09-16	Market Inspection	High	Closed
ENF-DEMO-011	2026-09-15	Follow-up Inspection	Medium	Closed
ENF-DEMO-012	2026-09-14	Market Inspection	High	Active
ENF-DEMO-013	2026-09-12	Factory Inspection	Low	Closed
ENF-DEMO-014	2026-09-10	Follow-up Inspection	Critical	Closed

Record 01: ENF-DEMO-001

Source citation: BIS MITRA Demo -> Enforcement -> ENF-DEMO-001

Case ID	ENF-DEMO-001
Inspection ID	INSP-DEMO-001
Inspection type	Market Inspection
Inspection date	2026-09-26
Location	Demo Wholesale Market, Pimpri
State	Maharashtra
Manufacturer	Aarohan Safety Works Pvt. Ltd. (Synthetic)
Product	Industrial Safety Helmet - ASW-H7
Standard number	IS DEMO 1001:2026
QCO reference	QCO DEMO 001:2026
Licence number	LIC-DEMO-26001
Inspection office	BIS MITRA Demo Office - Pune
Officer reference	OFF-DEMO-PN-001
Finding	Sampled 24 helmets; 4 helmets failed impact absorption at the crown zone in the synthetic test record.
Non-conformity	Impact absorption result below the fictional acceptance threshold defined for the helmet model; batch marking also had inconsistent trace code.
Severity	High
Evidence	Sealed sample set SS-DEMO-001; inspection photographs PH-DEMO-001 to PH-DEMO-004; test request TR-DEMO-001.
Units affected	180 helmets in identified batch
Hazard status	Potential injury hazard if helmet shell fails during an impact.
Action taken	Product seizure of identified batch; sale hold notice issued; follow-up test ordered.
Notice reference	NOTICE-DEMO-001
Seizure reference	SEIZ-DEMO-001
Seal order reference	-
Corrective action	Manufacturer to quarantine affected batch, replace non-conforming shell lots, and submit traceability reconciliation.
Follow-up date	2026-10-03
Case status	Pending Corrective Action
Closure date	-
Keywords	safety helmet; impact failure; seizure; market inspection; non-conformity
Synonyms	helmet inspection; head protection enforcement; failed helmet; seized safety gear
Surveillance reference	SURV-DEMO-001
Laboratory reference	LAB-DEMO-006

Record 02: ENF-DEMO-002

Source citation: BIS MITRA Demo -> Enforcement -> ENF-DEMO-002

Case ID	ENF-DEMO-002
Inspection ID	INSP-DEMO-002
Inspection type	Factory Inspection
Inspection date	2026-09-26
Location	Demo Appliance Park, Sriperumbudur
State	Tamil Nadu
Manufacturer	BlueRiver Home Appliances (Synthetic)
Product	Domestic Induction Cooking Appliance - BRH-IC2
Standard number	IS DEMO 1003:2025
QCO reference	QCO DEMO 003:2026
Licence number	LIC-DEMO-26003
Inspection office	BIS MITRA Demo Office - Chennai
Officer reference	OFF-DEMO-CH-002
Finding	Routine factory inspection found 2 production lots with dielectric withstand failures at final inspection.
Non-conformity	Insulation system did not meet the fictional dielectric withstand criterion for the affected lot.
Severity	High
Evidence	Factory sample FS-DEMO-002; final-test logs FL-DEMO-002; laboratory report TR-DEMO-002.
Units affected	420 appliances across 2 lots
Hazard status	Electrical shock risk if insulation weakness reaches the consumer.
Action taken	Production hold on affected lots; statutory-style notice issued; corrective action requested.
Notice reference	NOTICE-DEMO-002
Seizure reference	-
Seal order reference	-
Corrective action	Rework insulation process, segregate failed units, update final-test checklist, and provide verification batch.
Follow-up date	2026-10-05
Case status	Active
Closure date	-
Keywords	induction appliance; dielectric failure; factory inspection; electrical safety
Synonyms	induction cooker inspection; cooktop electrical non-conformity; insulation failure
Surveillance reference	SURV-DEMO-002
Laboratory reference	LAB-DEMO-001

Record 03: ENF-DEMO-003

Source citation: BIS MITRA Demo -> Enforcement -> ENF-DEMO-003

Case ID	ENF-DEMO-003
Inspection ID	INSP-DEMO-003
Inspection type	Market Inspection
Inspection date	2026-09-26
Location	Demo Retail Cluster, Whitefield
State	Karnataka
Manufacturer	FreshFold Packaging Works (Synthetic)
Product	Flexible Food Pouch - FP-21
Standard number	IS DEMO 1002:2025
QCO reference	QCO DEMO 002:2026
Licence number	-
Inspection office	BIS MITRA Demo Office - Bengaluru
Officer reference	OFF-DEMO-BL-003
Finding	Random retail samples showed migration test failure and incomplete traceability marking.
Non-conformity	Synthetic migration result exceeded the fictional limit for the selected simulant; pouch lacked production-batch trace code.
Severity	High
Evidence	Retail samples SM-DEMO-003; lab report TR-DEMO-003; package photographs PH-DEMO-011 to PH-DEMO-014.
Units affected	1,200 pouches across two supplied cartons
Hazard status	Potential food-contact contamination concern.
Action taken	Affected stock detained; notice issued to seller; additional samples drawn from distributor inventory.
Notice reference	NOTICE-DEMO-003
Seizure reference	SEIZ-DEMO-002
Seal order reference	-
Corrective action	Withdraw affected cartons, correct material formulation, restore traceability markings, and provide fresh compliance test evidence.
Follow-up date	2026-10-02
Case status	Under Investigation
Closure date	-
Keywords	food pouch; migration failure; packaging marking; market inspection
Synonyms	food packaging enforcement; flexible pouch non-conformity; migration complaint
Surveillance reference	SURV-DEMO-003
Laboratory reference	LAB-DEMO-003

Record 04: ENF-DEMO-004

Source citation: BIS MITRA Demo -> Enforcement -> ENF-DEMO-004

Case ID	ENF-DEMO-004
Inspection ID	INSP-DEMO-004
Inspection type	Factory Inspection
Inspection date	2026-09-24
Location	Demo Repair Materials Estate, Pune
State	Maharashtra
Manufacturer	NirmanSet Repair Materials LLP (Synthetic)
Product	Cementitious Repair Mortar - NSR-M25
Standard number	IS DEMO 1004:2024
QCO reference	QCO DEMO 004:2025
Licence number	LIC-DEMO-26004
Inspection office	BIS MITRA Demo Office - Pune
Officer reference	OFF-DEMO-PN-004
Finding	Compressive-strength samples from one production shift were below the fictional 28-day performance criterion.
Non-conformity	Average compressive strength below the required synthetic class value.
Severity	Medium
Evidence	Batch samples BS-DEMO-004; laboratory report TR-DEMO-004; batch production record BPR-DEMO-004.
Units affected	32 bags from one production shift
Hazard status	Performance risk in repair applications; no immediate acute hazard recorded.
Action taken	Corrective action notice issued and affected shift batch placed on controlled release.
Notice reference	NOTICE-DEMO-004
Seizure reference	-
Seal order reference	-
Corrective action	Adjust mix-control checks, investigate curing deviation, retest retained samples, and submit process correction record.
Follow-up date	2026-10-01
Case status	Pending Corrective Action
Closure date	-
Keywords	repair mortar; compressive strength; factory inspection; corrective action
Synonyms	mortar failure; repair material enforcement; strength non-conformity
Surveillance reference	SURV-DEMO-004
Laboratory reference	LAB-DEMO-004

Record 05: ENF-DEMO-005

Source citation: BIS MITRA Demo -> Enforcement -> ENF-DEMO-005

Case ID	ENF-DEMO-005
Inspection ID	INSP-DEMO-005
Inspection type	Market Inspection
Inspection date	2026-09-23
Location	Demo Building Materials Market, Ahmedabad
State	Gujarat
Manufacturer	PipeNova Drainage Systems (Synthetic)
Product	uPVC Drainage Pipe - UD-110
Standard number	IS DEMO 1011:2026
QCO reference	QCO DEMO 011:2026
Licence number	-
Inspection office	BIS MITRA Demo Office - Ahmedabad
Officer reference	OFF-DEMO-AH-005
Finding	Wall-thickness readings varied beyond the fictional dimensional tolerance in 3 of 10 samples.
Non-conformity	Dimensional deviation in pipe wall thickness.
Severity	Medium
Evidence	Sample set SM-DEMO-005; measurement sheet MS-DEMO-005; photographs PH-DEMO-021 to PH-DEMO-023.
Units affected	600 pipe lengths estimated from distributor stock
Hazard status	Long-term service reliability concern; no immediate injury hazard identified.
Action taken	Notice issued; distributor inventory placed on temporary hold pending independent verification.
Notice reference	NOTICE-DEMO-005
Seizure reference	-
Seal order reference	-
Corrective action	Provide extrusion-process calibration record and representative retest samples.
Follow-up date	2026-09-30
Case status	Active
Closure date	-
Keywords	uPVC pipe; wall thickness; dimensional non-conformity; market
Synonyms	drainage pipe inspection; pipe thickness failure; polymer pipe enforcement
Surveillance reference	SURV-DEMO-010
Laboratory reference	LAB-DEMO-002

Record 06: ENF-DEMO-006

Source citation: BIS MITRA Demo -> Enforcement -> ENF-DEMO-006

Case ID	ENF-DEMO-006
Inspection ID	INSP-DEMO-006
Inspection type	Factory Inspection
Inspection date	2026-09-22
Location	Demo Gas Appliance Zone, Jaipur
State	Rajasthan
Manufacturer	Ujjwal Hearth Devices Pvt. Ltd. (Synthetic)
Product	LPG Cabinet Heater - UHD-4K
Standard number	IS DEMO 1007:2025
QCO reference	QCO DEMO 007:2026
Licence number	LIC-DEMO-26007
Inspection office	BIS MITRA Demo Office - Jaipur
Officer reference	OFF-DEMO-JP-006
Finding	Gas leakage detected at the regulator connection during safety testing.
Non-conformity	Leak rate exceeded the fictional acceptance criterion during pressure stabilization.
Severity	Critical
Evidence	Factory sample FS-DEMO-006; gas test sheet GTS-DEMO-006; video evidence VID-DEMO-006.
Units affected	75 heaters from active assembly line
Hazard status	Acute fire and gas exposure hazard identified in the synthetic scenario.
Action taken	Emergency seal order issued for the affected assembly line; product movement stopped; samples retained.
Notice reference	NOTICE-DEMO-006
Seizure reference	SEIZ-DEMO-003
Seal order reference	SEAL-DEMO-001
Corrective action	Isolate regulator supplier lot, repair connection process, calibrate leak-testing equipment, and pass reinspection before restart.
Follow-up date	2026-09-29
Case status	Active
Closure date	-
Keywords	LPG heater; gas leak; emergency seal; critical hazard
Synonyms	gas appliance enforcement; heater leak; emergency sealing; safety shutdown
Surveillance reference	SURV-DEMO-006
Laboratory reference	LAB-DEMO-007

Record 07: ENF-DEMO-007

Source citation: BIS MITRA Demo -> Enforcement -> ENF-DEMO-007

Case ID	ENF-DEMO-007
Inspection ID	INSP-DEMO-007
Inspection type	Market Inspection
Inspection date	2026-09-20
Location	Demo Municipal Lighting Store, Chennai
State	Tamil Nadu
Manufacturer	PrabhaRoad Illumination Systems Ltd. (Synthetic)
Product	LED Road Luminaire - PRL-R120
Standard number	IS DEMO 1005:2026
QCO reference	QCO DEMO 005:2026
Licence number	LIC-DEMO-26005
Inspection office	BIS MITRA Demo Office - Chennai
Officer reference	OFF-DEMO-CH-007
Finding	Photometric performance was within the fictional limit, but one sample showed an environmental seal installation defect.
Non-conformity	Installation seal defect identified in one sampled unit.
Severity	Low
Evidence	Sample SM-DEMO-007; report TR-DEMO-007; site photographs PH-DEMO-031 to PH-DEMO-033.
Units affected	18 luminaires from one retail shipment
Hazard status	Environmental ingress may reduce expected service life; no immediate shock hazard recorded.
Action taken	Corrective action notice issued; distributor instructed to inspect retained stock.
Notice reference	NOTICE-DEMO-007
Seizure reference	-
Seal order reference	-
Corrective action	Replace defective seal batch and document supplier corrective action.
Follow-up date	2026-09-27
Case status	Closed
Closure date	2026-09-26
Keywords	LED luminaire; seal defect; corrective action; market inspection
Synonyms	lighting inspection; road light non-conformity; luminaire seal
Surveillance reference	SURV-DEMO-005
Laboratory reference	LAB-DEMO-005

Record 08: ENF-DEMO-008

Source citation: BIS MITRA Demo -> Enforcement -> ENF-DEMO-008

Case ID	ENF-DEMO-008
Inspection ID	INSP-DEMO-008
Inspection type	Factory Inspection
Inspection date	2026-09-18
Location	Demo Furniture Manufacturing Park, Gurugram
State	Haryana
Manufacturer	Kshetra Office Furnishings Co. (Synthetic)
Product	Modular Office Chair - KOF-M8
Standard number	IS DEMO 1008:2024
QCO reference	QCO DEMO 008:2024
Licence number	LIC-DEMO-26008
Inspection office	BIS MITRA Demo Office - Gurugram
Officer reference	OFF-DEMO-GR-008
Finding	Fatigue cycling revealed premature caster housing loosening after accelerated testing.
Non-conformity	Durability result below fictional test-cycle threshold.
Severity	Medium
Evidence	Chair sample FS-DEMO-008; fatigue report TR-DEMO-008; process checklist PC-DEMO-008.
Units affected	90 chairs in a production run
Hazard status	Stability concern that may cause a chair tip incident.
Action taken	Production hold on affected caster lot and corrective action notice.
Notice reference	NOTICE-DEMO-008
Seizure reference	-
Seal order reference	-
Corrective action	Replace caster component, strengthen incoming inspection, and pass follow-up fatigue test.
Follow-up date	2026-09-25
Case status	Closed
Closure date	2026-09-26
Keywords	office chair; fatigue test; caster failure; corrective action
Synonyms	furniture enforcement; chair durability issue; seating inspection
Surveillance reference	SURV-DEMO-007
Laboratory reference	LAB-DEMO-010

Record 09: ENF-DEMO-009

Source citation: BIS MITRA Demo -> Enforcement -> ENF-DEMO-009

Case ID	ENF-DEMO-009
Inspection ID	INSP-DEMO-009
Inspection type	Market Inspection
Inspection date	2026-09-17
Location	Demo Solar Hardware Market, Ahmedabad
State	Gujarat
Manufacturer	SuryaGrid Mounting Systems Pvt. Ltd. (Synthetic)
Product	Rooftop Solar PV Mounting System - SGM-RF2
Standard number	IS DEMO 1009:2026
QCO reference	QCO DEMO 009:2026
Licence number	LIC-DEMO-26009
Inspection office	BIS MITRA Demo Office - Ahmedabad
Officer reference	OFF-DEMO-AH-009
Finding	Fastener pull-out test failed on one mounting configuration.
Non-conformity	Joint integrity below fictional pull-out resistance requirement.
Severity	High
Evidence	Sample SM-DEMO-009; report TR-DEMO-009; installation photographs PH-DEMO-041 to PH-DEMO-044.
Units affected	60 mounting kits in distributor stock
Hazard status	Structural detachment risk under wind loading.
Action taken	Stock detention notice issued and distributor instructed not to dispatch affected configuration.
Notice reference	NOTICE-DEMO-009
Seizure reference	SEIZ-DEMO-004
Seal order reference	-
Corrective action	Replace fastener batch, verify torque controls, and submit load-test evidence.
Follow-up date	2026-09-30
Case status	Under Investigation
Closure date	-
Keywords	solar mounting; fastener pull-out; high risk; market inspection
Synonyms	PV mounting enforcement; solar structure failure; fastener non-conformity
Surveillance reference	SURV-DEMO-008
Laboratory reference	LAB-DEMO-009

Record 10: ENF-DEMO-010

Source citation: BIS MITRA Demo -> Enforcement -> ENF-DEMO-010

Case ID	ENF-DEMO-010
Inspection ID	INSP-DEMO-010
Inspection type	Market Inspection
Inspection date	2026-09-16
Location	Demo Kitchenware Bazaar, Kochi
State	Kerala
Manufacturer	Sampoorna Kitchenware Industries (Synthetic)
Product	Stainless Steel Food-Contact Utensils - SKI ProLine Set
Standard number	IS DEMO 1006:2025
QCO reference	QCO DEMO 006:2025
Licence number	LIC-DEMO-26006
Inspection office	BIS MITRA Demo Office - Kochi
Officer reference	OFF-DEMO-KO-010
Finding	Metal-contact sample showed fictional elemental migration above the permitted value.
Non-conformity	Extractable nickel-equivalent migration exceeded the synthetic acceptance criterion.
Severity	High
Evidence	Sample set SM-DEMO-010; chemistry report TR-DEMO-010; package label photograph PH-DEMO-051.
Units affected	240 utensil sets
Hazard status	Potential food-contact exposure concern.
Action taken	Affected stock seized pending verification; manufacturer notice issued.
Notice reference	NOTICE-DEMO-010
Seizure reference	SEIZ-DEMO-005
Seal order reference	-
Corrective action	Trace alloy batch, segregate stock, verify material chemistry, and submit replacement test results.
Follow-up date	2026-09-28
Case status	Closed
Closure date	2026-09-25
Keywords	food-contact utensil; migration; seizure; chemistry
Synonyms	kitchenware enforcement; stainless utensil failure; food contact non-conformity
Surveillance reference	SURV-DEMO-009
Laboratory reference	LAB-DEMO-003

Record 11: ENF-DEMO-011

Source citation: BIS MITRA Demo -> Enforcement -> ENF-DEMO-011

Case ID	ENF-DEMO-011
Inspection ID	INSP-DEMO-011
Inspection type	Follow-up Inspection
Inspection date	2026-09-15
Location	Demo Appliance Park, Pune
State	Maharashtra
Manufacturer	HydroSafe Appliances (Synthetic)
Product	Electric Storage Water Heater - HSA-E25
Standard number	IS DEMO 1014:2025
QCO reference	QCO DEMO 012:2026
Licence number	LIC-DEMO-26010
Inspection office	BIS MITRA Demo Office - Pune
Officer reference	OFF-DEMO-PN-011
Finding	Follow-up verified completion of heating cut-off correction and test-process revision.
Non-conformity	Previous thermal cut-off non-conformity corrected; verification sample passed.
Severity	Medium
Evidence	Follow-up sample FS-DEMO-011; verification report TR-DEMO-011; corrective action closure record CAR-DEMO-011.
Units affected	Previous affected lot of 110 heaters
Hazard status	Previous overheating concern controlled after corrective action.
Action taken	Follow-up inspection passed; closure recommendation recorded.
Notice reference	NOTICE-DEMO-011
Seizure reference	-
Seal order reference	-
Corrective action	Maintain revised cut-off calibration schedule and retain quarterly verification evidence.
Follow-up date	-
Case status	Closed
Closure date	2026-09-18
Keywords	water heater; follow-up inspection; thermal cut-off; closed case
Synonyms	geyser enforcement; heater corrective action; electrical follow-up
Surveillance reference	SURV-DEMO-011
Laboratory reference	LAB-DEMO-001

Record 12: ENF-DEMO-012

Source citation: BIS MITRA Demo -> Enforcement -> ENF-DEMO-012

Case ID	ENF-DEMO-012
Inspection ID	INSP-DEMO-012
Inspection type	Market Inspection
Inspection date	2026-09-14
Location	Demo Hardware Market, Lucknow
State	Uttar Pradesh
Manufacturer	Aarohan Safety Works Pvt. Ltd. (Synthetic)
Product	Industrial Safety Helmet - ASW-H9
Standard number	IS DEMO 1001:2026
QCO reference	QCO DEMO 001:2026
Licence number	LIC-DEMO-26002
Inspection office	BIS MITRA Demo Office - Lucknow
Officer reference	OFF-DEMO-LK-012
Finding	Retention-system test failed on 2 of 6 sampled helmets.
Non-conformity	Chin-strap retention force below the fictional threshold.
Severity	High
Evidence	Sample set SM-DEMO-012; test report TR-DEMO-012; inspection photos PH-DEMO-061 to PH-DEMO-063.
Units affected	90 helmets from one shipment
Hazard status	Potential loss of helmet retention during impact.
Action taken	Affected shipment seized; notice issued to distributor and manufacturer.
Notice reference	NOTICE-DEMO-012
Seizure reference	SEIZ-DEMO-006
Seal order reference	-
Corrective action	Quarantine shipment, verify retention-system supplier lot, and submit replacement sample set.
Follow-up date	2026-10-01
Case status	Active
Closure date	-
Keywords	helmet; retention failure; seizure; high severity
Synonyms	chin strap enforcement; helmet retention; PPE inspection
Surveillance reference	SURV-DEMO-012
Laboratory reference	LAB-DEMO-006

Record 13: ENF-DEMO-013

Source citation: BIS MITRA Demo -> Enforcement -> ENF-DEMO-013

Case ID	ENF-DEMO-013
Inspection ID	INSP-DEMO-013
Inspection type	Factory Inspection
Inspection date	2026-09-12
Location	Demo Polymer Works, Bhubaneswar
State	Odisha
Manufacturer	FreshFold Packaging Works (Synthetic)
Product	Flexible Food Pouch - FP-21
Standard number	IS DEMO 1002:2025
QCO reference	QCO DEMO 002:2026
Licence number	-
Inspection office	BIS MITRA Demo Office - Bhubaneswar
Officer reference	OFF-DEMO-BB-013
Finding	Factory traceability review found adhesive batch records not mapped to finished-goods lots.
Non-conformity	Traceability documentation incomplete for one production day.
Severity	Low
Evidence	Batch records BR-DEMO-013; trace matrix TM-DEMO-013; interview note IN-DEMO-013.
Units affected	Estimated 3 production lots
Hazard status	No direct hazard established; traceability weakness reduces recall effectiveness.
Action taken	Notice issued and documentary corrective action requested.
Notice reference	NOTICE-DEMO-013
Seizure reference	-
Seal order reference	-
Corrective action	Implement lot-linking control and resubmit traceability matrix for verification.
Follow-up date	2026-09-26
Case status	Closed
Closure date	2026-09-26
Keywords	food pouch; traceability; factory inspection; documentation
Synonyms	packaging traceability; batch-record non-conformity; factory enforcement
Surveillance reference	SURV-DEMO-003
Laboratory reference	LAB-DEMO-003

Record 14: ENF-DEMO-014

Source citation: BIS MITRA Demo -> Enforcement -> ENF-DEMO-014

Case ID	ENF-DEMO-014
Inspection ID	INSP-DEMO-014
Inspection type	Follow-up Inspection
Inspection date	2026-09-10
Location	Demo Gas Appliance Zone, Jaipur
State	Rajasthan
Manufacturer	Ujjwal Hearth Devices Pvt. Ltd. (Synthetic)
Product	LPG Cabinet Heater - UHD-4K
Standard number	IS DEMO 1007:2025
QCO reference	QCO DEMO 007:2026
Licence number	LIC-DEMO-26007
Inspection office	BIS MITRA Demo Office - Jaipur
Officer reference	OFF-DEMO-JP-014
Finding	Follow-up confirmed leak-test recalibration and replacement of affected regulator lot.
Non-conformity	Previous leakage finding corrected; verification samples passed all required synthetic gas-safety checks.
Severity	Critical
Evidence	Verification report TR-DEMO-014; calibration certificate CAL-DEMO-014; closure photographs PH-DEMO-071 to PH-DEMO-074.
Units affected	75 heaters from previously held lot
Hazard status	Previous hazard controlled; no residual leakage found in verification sample.
Action taken	Seal action lifted after verification; case closed with monitoring note.
Notice reference	NOTICE-DEMO-006
Seizure reference	SEIZ-DEMO-003
Seal order reference	SEAL-DEMO-001
Corrective action	Continue enhanced leak testing for three production batches.
Follow-up date	-
Case status	Closed
Closure date	2026-09-12
Keywords	LPG heater; seal lifted; follow-up; closure
Synonyms	gas appliance reinspection; leak correction; enforcement closure
Surveillance reference	SURV-DEMO-013
Laboratory reference	LAB-DEMO-007

Demo note

Use the demo_id, case IDs, inspection IDs, laboratory IDs, standard numbers, QCO references and licence numbers as stable synthetic identifiers for MITRA retrieval and source citation.