
ZINWR ZIRWR FUNR, RWR - OLP 101-102 WJR_INT & Intication - 7 i mer Control Reley 101-102 WJR JSLR - 7 imer Control
101-102 WJR JR -> 1205ec Reley 101=102. WIRI -> Timer control relong *161-162-XR - mid Strong Prevention Recog 101-102 NWCR- Point supply control prop 101/102 WLR 101 WNR , 101 TIA 102 FPR 101/corNURIN 102 WMR 101 162 ZINWR 101/102 XR 101/102 RC 101 WNR EWAR 101TPR 100 www 109 TOR



NWCRI 101/102 101/102 101/102 10/1/102 10/1/10) NWR-IN RWCR WORL WORDR NWKR * Physical Point operard Relays: Olp Relays: RNR/NWR -> -Normal/Reverse Point operation Relay NINCR/RWCR -> Normal/Reverse point control anday IlP Relays -. NWR-IN/RWRIN - Normal/Reverse latch Relay NWKR/RWKR - Normal/Reverse point indication Relays Steps by Step Pick up Roint Relays .-NWR/RWR -> Normal/Reverse Point Operation Rg NWR-IN / RWR-IN -> Latch Relays, ensures salty to point methine NWCR IRWCR -> supply extends Relay upto 8-12 SCC to point

NWKR / RWKR -> Detection Relays