

NOTES:
Do NOT change ROCKET_IGNITE,
pin default reset state is High-Z
w/ pulldown resistor. Other pins
can be configured in EEPROM
at boot time.

1000


- * Buffer btw rocket—ready signal and BB, ign. board, etc?
- * Umbilical connection state
- * Ignition fuse state


Portland State Aerospace Society http://psas.pdx.edu/ Sheet: /BeagleBone Black Cape/ File: beaglebone_cape.sch

Title: LTC3 BeagleBone Black Cape Interface


 Size: B
 Date: 2016-01-30
 Rev: A

 KiCad E.D.A. kicad 4.0.0rc1a-stable
 Id: 5/7





External Device Power



External Device Triggers

- TODO:

 * Determine values for bleeder resistor
 and filter capacitor on each output connector.

 * Pick new PolyFuses, 0.5—1.0A max.

Portland	State	Aerospace	Society	<http: <="" th=""><th>/psas.pdx.edu/></th></http:>	/psas.pdx.edu/>

Sheet: /External Device Power & Triggers/
File: external_devices.sch

Title: LTC3 External Power & Triggers

Title: LICS	External Power & Iriggers	
Size: B	Date: 2016-01-30	

Rev: A Id: 7/7 KiCad E.D.A. kicad 4.0.0rc1a-stable