There's a Problem...



Problem... Weak Sheet

- Even given the solution presented, multiple methods can be applied to create the desired geometry.
- A bad approach to cutting out the openings.
 This sequence results in weakened, bent sheet metal.



