## Z-Axis Motor Mount - WA-090-S

Part in Context

This part serves as a simple mount for the z-axis motor. The four small holes is aligned for the motor frame and the four larger holes will mount to the z-axis bearing support (WA-080-S). The cut--through will allow for an Allen wrench to access the coupling set screw.

