



# MASS-VIEW

## Meter, Regulator and Controller

MASS-VIEW  
Hook-up diagram

Output: 0....5Vdc  
Supply voltage: +15Vdc....+24Vdc



**Note :**  
0V power (pin 4) **and** 0V sense (pin 8) should be separately connected to the 0V terminal at the power supply.