



A

A



B

B



C

C

A

A

B


B

C


C

D

D




A



A

B





B

C

D

## Contactor Feedback Supply from External Supply




A

A

One connector for each contactor:  
 - Coil supply  
 - Feedback contact

B

B



C


C

D

D


A

A



B

B





C


C



D


D














Isolated normally open contacts connector

X2001	
ISONOC_0_POSITIVE	1
ISONOC_1_POSITIVE	2
ISONOC_2_POSITIVE	3
ISONOC_3_POSITIVE	4
ISONOC_4_POSITIVE	5
ISONOC_5_POSITIVE	6
ISONOC_0_NEGATIVE	7
ISONOC_1_NEGATIVE	8
ISONOC_2_NEGATIVE	9
ISONOC_3_NEGATIVE	10
ISONOC_4_NEGATIVE	11
ISONOC_5_NEGATIVE	12

molex\_microfit\_3\_06x2\_THT

A

A

B

B

C

C

D

D

Connector for optional FPGA extension board

