







You can cut all legs from one beam without changing saw angles.

Lay beam like in isometry on your miter saw.

Set saw angles:

- Primary angle=-4.5
- Secondary angle=4.5 (cut in feeddirection)

Start first cut at end of the beam

Then make legs by marking lengths

and feed the beam through the saw

without changing the orientation of beam

afterwards you can cut the orthogonal cuts where the beams touch

Parts

You need 4 beams of around 817mm.
That's total length of 3270mm

Tomy

designer	manual license	design license
Archiyou	CC BY-NC	CC BY-NC

params
H:758 BW:100 LO:60

metrics
TW:185 mm TD:185 mm

v0 at 22-9-2025, 15:40:18