
Residual allocation error: measured equilibrium is q=u, not q=0.9u
Wrench traces are model estimates, not independent force measurements

Sensor frame fixed



Sensor + DC gain fixed

