

GOBI M350 Fieldbook — Equipment Checklist

APPN Aerial SOP — Locked revision 1.0

Equipment Checklist

Note

Ensure batteries for all equipment are fully charged before heading to the field. Ensure charging cables are available for necessary equipment.

- ☐ **Aircraft**
- ☐ DJI M350
- ☐ Aircraft batteries and spares
- ☐ Landing gear
- ☐ Landing pad
- ☐ Spare parts
- ☐ Tools
- ☐ Logbook
- ☐ **Radio Control Transmitter / Ground Control Station**
- ☐ **GRYFN Gobi**
- ☐ Gobi system (power once each month to charge the RGB camera internal battery)
- ☐ Power cables, chargers
- ☐ Ethernet cable (and dongle if needed)
- ☐ SD card
- ☐ *Capture* and *survey* polygon files
- ☐ **Ground reference kit**
- ☐ 2 x Reflectance calibration panels (11%, 30%, 56%, 82%)
- ☐ 1 x Calibration validation panels (20%, 45%)
- ☐ 5 × Propeller Aeropoints or other ground control points (GCPs) and/or RTK GNSS system
- ☐ 2 × folding tables to elevate panels
- ☐ *If over 30 km from a single CORS base station*, a portable RTK base station ([link to GRYFN gitbook](#))
- ☐ **Accessories**
- ☐ Safety gear (signage and high-vis vests)
- ☐ Aeronautical radio
- ☐ Field laptop and spare batteries
- ☐ External storage media
- ☐ Water, food, esky, sunscreen, bug spray, first aid kit, etc.
- ☐ Spirit bubble, spirit level (or angle measurement) and measuring tape
- ☐ Portable fan (for cooling GOBI during data offload)
- ☐ External power brick (for charging UAV RC)

Note

The **Ground reference kit** above assumes the Standard Dual ELM panel flight design. Other flight designs may require additional equipment (e.g. extra reflectance panel sets, additional GCPs and folding tables for multi-flight captures, or extra targets for validation flights). See the Standard Flight Procedure and the Validation Flight Procedure for the full equipment requirements of each design.