




Power supply		Sensors	
Fichier: PSU.kicad_sch		Fichier: sensors.kicad_sch	
	mcu	LED	
	Fichier: mcu.kicad_sch	LED Fichier: led.kicad_sch	















```
XSDN0 = PC2
XSDN1 = PC15
XSDN2 = PC12
XSDN3 = PB9
XSDN4 = PB6
                                                                  LED0 = PC3
LED1 = PC0
LED2 = PC13
LED3 = PC10
LED4 = PB7
INTO = PC1
INT1 = PC14
INT2 = PC11
INT3 = PB8
INT4 = PB5
INT5 = PD4
                               XSDN5 = PB3
                                                                   LED5 = PB4
INT6 = PD1
                               XSDN6 = PD2
                                                                   LED6 = PD3
                               XSDN7 = PC9
XSDN8 = PA12
INT7 = PC8
                                                                   LED7 = PD0
                                                                    LED8 = PA15
INT9 = PC6
                               XSDN9 = PC7
                                                                    LED9 = PD8
INT10 = PB15
                               XSDN10 = PA8
                                                                    LED10 = PA9
                                                                  LED10 = PA9

LED11 = PB14

LED12 = PB11

LED13 = PB1

LED14 = PC4

LED15 = PA5
INT11 = PB12
INT12 = PB2
                               XSDN11 = PB13
                              XSDN11 = PB10
XSDN13 = PB0
XSDN14 = PA7
XSDN15 = PA4
INT13 = PC5
INT14 = PA6
INT15 = PA3
```

