

By default, I2C is enabled because CS is pulled high