Technician Service Report

Header
Report:
The 730 EJ model with serial number 7301480 underwent an inspection with ID 2 on August 11,
2024, at Vellore. The service meter read 18741 at the time of inspection. This report is based solely
on the provided data and contains no additional information.
Tires
The right front tire needs replacement due to low tire pressure, while the other tires are in good
condition.
Battery
Report:
The battery in question is a CAT brand with a voltage of 500V. The water level is currently at a good
level. There are no signs of leaks or rust on the battery, indicating that it is in good condition.
Exterior
Tires: All tires are inflated to the recommended PSI.
Brake lights: Functioning properly.
Headlights: Functioning properly.

Taillights: Functioning properly.			
Windshield wipers: Functioning properly.			
Interior:			
Seat belts: All seat belts are functioning properly.			
Airbags: All airbags are in place and appear to be functioning properly.			
Steering: Steering is responsive and			
Brakes			
Report:			
The fluid level of the brakes is at an acceptable level. However, the front brake pads need to be			
replaced soon as they have worn down significantly. The rear brake pads are still in good condition			
and do not require immediate attention. The emergency brake is functioning properly.			
Engine			
Report:			
report.			
The engine oil condition is good, despite its black color. The brake fluid condition, however, is poor,			
as it is clear. The vehicle does not have any major damage or noticeable leaks. It is recommended			
to replace the brake fluid to ensure proper functioning and safety of the vehicle.			
Customer Feedback			
Customer Feedback			
Date: 2022-01-01			

_		
Re	nn	rt.
110	ν	ιι.

On January 1, 2022, a customer provided feedback stating that they received good service. No further details were provided.