- look around for industry format for Hight data
- minimize # of hardware components - implement one at a time
- define an interface for how each part connects to the others
- consider using different hardware boards for AHRS/INS and pilot input
- image stabilization in a vibrating plane