#### ARKTECH PHILIPPINES IN

17 6B.PHASE 1-A FIRST PHILIPPINE INDUSTRIAL PARK, STO. TOMAS, BAT.
TEL 63(43)405-6140~2

A No	irst Philippine Industrial Park, Sto. Tomas, . Batangas  B  Part No  XRS02057-7008		1 2 3 C		Run Cosi	ts Per Hour		8.73	Arkte	ch's Propose		1											
m No	B Part No		3		Indirect Lat					ich is Proposei	d Costs												,
m No	Part No					bour per Hour		2.64	Arkto	ch's Propose	d Costs												
m No	Part No		С	T		our per Hour	<b>,</b>	1.74	Arkte	ch's Propose											· · · · · · · · · · · · · · · · · · ·		
	· · · · · · · · · · · · · · · · · · ·			D	E	F	G	Н	- 1	J	К	L Committee	M	N	0	P	, Q	R	S	T	U	V	
ŀ	VDC020E7 7009		Process	Qty per Hr	Material Cost Per Part	Manning No	Run Cost Per part	Direct labor per part	Indirect Labor Per Part	Total Facility Costs Per Part	Anodising	Priming	Brush finish	Passivatio n	Etching	Packaging material	Material Cost + Finishing Cost	Overhead Uplift (Material, Processing & Finishing Costs) 5%	(Material + Finishing Cost)+ (Overhead Uplift)+(Total Facility Costs)	General Overhead Uplift 10%	Profit Uplift 10%	Total Part cost	Condition and Remarks
I	VICTOR (	В	LASER	2	\$0.05	1	\$3.60	\$0.72	\$1.09	\$5.41	\$0.08	\$0.02	\$-	\$-	\$-	\$0.22	•						QTY:1-2
L			file	79		1	\$0.11	\$0.02	\$0.03	\$0.17													
	UPPER DOOR SEAL SPACER		Clean	13110		1	\$0.00	\$0.00	\$0.00	\$0.00				1							-		
	······································		Part Marking	87		1	\$0.10	\$0.02	\$0.03	\$0.15													
·			INS	6		1	\$1.43	\$0.29	\$0.43	\$2.15													
								100															
			Total Cost		\$0.05					\$7.87	\$0.08	\$0.02	\$-	\$-	\$-	\$0.22	\$0.37	\$0.02	\$8.26	\$0.83	\$0.83	\$9.91	
	XRS02057-7008	В	LASER	5	\$0.05	1	\$1.67	\$0.33	\$0.51	\$2.51	\$0.08	\$0.02	\$-	\$-	\$-	\$0.22						1	. QTY:3-5
	UDDED DOOD STAL SPACED		File	101		1	\$0.09	\$0.02	\$0.03	\$0.13													
	UPPER DOOR SEAL SPACER		Clean	13110		1	\$0.00	\$0.00	\$0.00	\$0.00													
			Part Marking	87		1	\$0.10	\$0.02	\$0.03	\$0.15													
2	-		INS	18		1	\$0.48	\$0.09	\$0.14	\$0.72													
			7																				
		-	Total Cost		\$0.05					\$3.51	\$0.08	\$0.02	\$-	\$-	\$-	\$0.22	\$0.37	\$0.02	\$3.89	\$0.39	\$0.39	\$4.67	
	XRS02057-7008	В	LASER	8	\$0.05	1	\$1.07	\$0.21	\$0.33	\$1.61	\$0.08	\$0.02	\$-	\$-	\$-	\$0.22						7	QTY :6-10
		_	File	119		1	\$0.07	\$0.01	\$0.02	\$0.11											<b>†</b>		
	UPPER DOOR SEAL SPACER		Clean	13110		1	\$0.00	\$0.00	\$0.00	\$0.00													
			Part Marking	90		1	\$0.10	\$0.02	\$0.03	\$0.15				1									
3			INS	36		1	\$0.24	\$0.05	\$0.07	\$0.36													
-				<b>T</b>							,										1		
833 <b>)</b> –		$\vdash$		<b>†</b>	-													1		<b>1</b>	<b>†</b>		
		$\vdash$	Total Cost	1	\$0.05	<del>                                     </del>	<del>                                     </del>			\$2.23	\$0.08	\$0.02	\$-	\$-	\$-	\$0.22	\$0.37	\$0.02	\$2.62	\$0.26	\$0.26	\$3.14	
5353	XRS02057-7008	В	LASER	12	\$0,05	.1	\$0.72	\$0.14	\$0.22	\$1.08	\$0.08	\$0.02	\$-	\$-	\$-	\$0.22		<del> </del>		-		\ \ \	QTY: 11-25
-	***************************************		File	131		1	\$0.07	\$0.01	\$0.02	\$0.10		<u> </u>		<del>                                     </del>	· ·					<del>                                     </del>			
	UPPER DOOR SEAL SPACER		Clean	13110		1	\$0.00	\$0.00	\$0.00	\$0.00				1		·							
-			Part Marking	90		1	\$0.10	\$0.02	\$0.03	\$0.15	-,						<b></b>	<b> </b>		<u> </u>			
4			INS	66		٦	\$0.13	\$0.03	\$0.04	\$0.20				1			<b></b>	<b> </b>					
	· · · · · · · · · · · · · · · · · · ·			1										<u> </u>	· · · ·			<b></b>	<b></b>				
				<b>†</b>																	<b>†</b>		
			Total Cost	<b> </b>	\$0.05	<u> </u>				\$1.53	\$0.08	\$0.02	<b>\$</b> -	\$-	\$-	\$0.22	\$0.37	\$0.02	\$1.92	\$0.19	\$0.19	\$2.30	

#### ARKTECH PHILIPPINES INC

)T 6B,PHASE 1

T 6B,PHASE 1-A FIRST PHILIPPINE INDUSTRIAL PARK, STO. TOMAS, BATANG,

## ---- Q U O T A T I O N ----

	B/E AEROSPACE - PHILI	PPIN	ES																				API2021-273
	First Philippine Industrial Park, Sto. Tomas,		1		Run Cost	s Per Hour		8.73	Arkte	ch's Propose	d Costs												
	Batangas		2		Indirect Lat	our per Hour		2.64	Arkte	ch's Propose	d Costs												
			3			our per Hour		1.74	Arkte	ch's Propose							·			r		1	
A	В		С	D	. E	F	G	н	<u> </u>	J	K	L	M	N	0	Р	Q	R	<u> </u>	Т	U	V	
em No	Part No		Process	Qty per Hr	Material Cost Per Part	Manning No	Run Cost Per part	Direct labor per part	Indirect Labor Per Part	Total Facility Costs Per Part	Anodising	Priming	Brush finish	Passivatio n	Etching	Packaging material	Material Cost + Finishing Cost	Overhead Uplift (Material, Processing & Finishing Costs) 5%	(Material + Finishing Cost)+ (Overhead Uplift)+(Total Facility Costs)	General Overhead Uplift 10%	Profit Uplift 10%	Total Part cost	Condition and Remarks
410.55	XRS02057-7008	В	LASER	20	\$0.05	1	\$0.44	\$0.09	\$0.13	\$0.65	\$0.08	\$0.02	\$-	\$-	\$-	\$0.22							QTY: 26-50
H	X11002001 7000	_	file	146		1	\$0.06	\$0.01	\$0.02	\$0.09											<b> </b>		
	UPPER DOOR SEAL SPACER	<u> </u>	Clean	13110		1	\$0.00	\$0.00	\$0.00	\$0:00				<u> </u>									
ŀ			Part Marking	90		1	\$0.10	\$0.02	\$0.03	\$0.15				<del> </del>							-		
5			INS	164		1	\$0.05	\$0.01	\$0.02	\$0.08											1		
				-										1	<b></b>						T	ļ, — i	
			Total Cost		\$0.05					\$0.97	\$0.08	\$0.02	\$-	\$-	\$-	\$0.22	\$0.37	\$0.02	\$1.36	\$0.14	\$0.14	\$1.63	
4	· · · · · · · · · · · · · · · · · · ·						40.00		** **					<u> </u>		\$0.22	40.01	+0.02	<b>V</b> 1.00	40.11		41.00	QTY : 51 onwards
-	XRS02057-7008	В	LASER	30 164	\$0.05	1	\$0.30	\$0.06 \$0.01	\$0.09	\$0.44 \$0.08	\$0.08	\$0.02	\$-	\$-	\$-	\$0.22				ļ	<del> </del>		QTT. OT OTHER
	UPPER DOOR SEAL SPACER		Fite	1		1	\$0.05		\$0.02					1	_						-		
	· · · · · · · · · · · · · · · · · · ·	ļ	Clean	13110		1	\$0.00	\$0.00	\$0.00	\$0.00			*				ļ	ļ		ļ			
6		-	Part Marking	90		1	\$0.10	\$0.02	\$0.03	\$0.15 \$0.04				<b></b>							ļ		
		-	INS	328		11	-\$0.03	\$0.01	\$0.01	\$0.04				<del> </del>				<del> </del>				<del>                                     </del>	
1000000 10000000		ļ												<u> </u>			-				+		
-														<b></b>	<u> </u>					<u> </u>	<del> </del>	64.00	
585			Total Cost	ļ	\$0.05					\$0.71	\$0.08	\$0.02	\$-	\$-	\$-	\$0.22	\$0.37	\$0.02	\$1.10	\$0.11	\$0.11	\$1.32	
	XRS02057-7010	В	LASER	2	\$0.64	1	\$4.47	\$0.89	\$1.35	\$6.72	\$1.54	\$0.39	· \$-	\$-	\$-	\$0.56				<u> </u>	1		QTY:1-2
	UPPER DOOR SEAL DOUBLER		FILE	16		1	\$0.55	\$0.11	\$0.17	\$0.82							ļ			ļ	ļ		
	OT LINDON OLDE DOODLEN		Clean	656		1	\$0.01	\$0.00	\$0.00	\$0.02						ļ	ļ				ļ		
			Part Marking	87		1	\$0.10	\$0.02	\$0.03	\$0.15				ļ						<u> </u>	<del> </del>		
7			INS	6		1	\$1.54	\$0.31	\$0.47	\$2.31												,	
														·									
																	L				<u> </u>		
		1	Total Cost		\$0.64					\$10.02	\$1.54	\$0.39	\$-	\$-	\$-	\$0.56	\$3.12	\$0.16	\$13.29	\$1.33	\$1.33	\$15.95	
	XRS02057-7010	В	., LASER	3	\$0.64	1	\$2.50	\$0.50	\$0.76	\$3.76	\$1.54	\$0.39	\$-	\$-	\$-	\$0.56	1						QTY:3-5
-		T	FILE	17		1	\$0.52	\$0.10	\$0.16	\$0.78				1	1					1	1		
	UPPER DOOR SEAL DOUBLER		Clean	656		1	\$0.01	\$0.00	\$0.00	\$0.02				1.			1	1					
			Part Marking	87		1	.\$0.10	\$0.02	\$0.03	\$0.15					1			1					
8			INS	17		1	\$0.51	\$0.10	\$0.16	\$0.77							1-						
				1		<u> </u>	T								1			1			1		
h		1		<del>                                     </del>	<b></b>			<del> </del>							<b>T</b>			<u> </u>					
		<del>                                     </del>	Total Cost	1	\$0.64	<u> </u>	<b>-</b>	<del>                                     </del>		\$5.48	\$1,54	\$0.39	\$-	\$-	\$-	\$0.56	\$3.12	\$0.16	\$8.75	\$0.88	\$0.88	\$10.50	-

#### ARKTECH PHILIPPINES IN

1T 6B,Phase 1-A FIRST PHILIPPINE INDUSTRIAL PARK, STO. TOMAS, BAT TEL 63(43)405-6140~2

F			IES																					API2021-273
	irst Philippine Industrial Park, Sto. Tomas,		1		Run Cos	its Per Hour		8.73	Arkte	ch's Propose	d Costs													
	Batangas		· 2		Indirect La	bour per Hour	,	2.64	Arkte	ch's Propose	d Costs													
		-	3		Direct Lat	our per Hour		. 1.74	Arkte	ch's Propose	d Costs					····								
Α.	В		С	D	E	F	G	н	1	J	K	L	М	N	0	Р	Q	R	S	Т	U	V .	·	
item No	Part No		Process	Qty per Hr	Material Cost Per Part	.Manning No	Run Cost Per part	Direct labor per part	indirect Labor Per Part	Total Facility Costs Per Part	Anodising	Priming	Brush finish	Passivatio n	Etching	Packaging material	Material Cost + Finishing Cost	Overhead Uplift (Material, Processing & Finishing Costs) 5%	(Material + Finishing Cost)+ (Overhead Uplift)+(Total Facility Costs)	General Overhead Uplift 10%	Profit Uplift 10%	Total Part cost		Condition and Remarks
	XRS02057-7010	В	LASER	5	\$0.64	1	\$1.89	\$0.38	\$0.57	\$2.83	\$1.54	\$0.39	\$-	\$-	\$-	\$0.56							·	QTY:6-10
			FILE	17		1	\$0.51	\$0.10	\$0.15	\$0.76														
	UPPER DOOR SEAL DOUBLER		Clean	656		1	\$0.01	\$0.00	\$0.00	\$0.02											-			
			Part Marking	87		1	\$0.10	\$0.02	\$0.03	\$0.15												1		
9 -	· · · · · · · · · · · · · · · · · · ·	<del>                                     </del>	INS	35		1	\$0.25	\$0.05	\$0.08	\$0.38														
	•							•																
T									-															
			Total Cost		\$0.64					\$4.15	\$1.54	\$0.39	\$-	\$-	\$-	\$0.56	\$3.12	\$0.16	\$7.42	\$0.74	\$0.74	\$8.91		
	XRS02057-7010	В	LASER	6	\$0.64	1	\$1.53	\$0.31	\$0.46	\$2.30	\$1.54	\$0,39	\$-	\$-	\$-	\$0.56								QTY:11-25
			FILE	17		1	\$0.50	\$0.10	\$0.15	\$0.76								ŀ		·				
	UPPER DOOR SEAL DOUBLER		Clean	656		1	\$0.01	\$0.00	\$0.00	\$0.02														
			Part Marking	87		. 1	\$0.10	\$0.02	\$0.03	\$0.15														
10			INS	62		1	\$0.14	\$0.03	\$0.04	\$0,21														
																		1						
		1																						
		1	Total Cost		\$0.64					\$3.44	\$1.54	\$0.39	\$-	\$-	\$-	\$0.56	\$3.12	\$0.16	\$6.71	\$0.67	\$0.67	\$8.05		
	XRS02057-7010	В	LASER	7	\$0.64	1	\$1.25	\$0.25	\$0.38	\$1.87	\$1.54	\$0.39	\$-	5-	\$-	\$0.56	1	· · · · · · · · · · · · · · · · · · ·			1	1		QTY:26-50
-		<del>-</del> -	FILE	18		1	\$0.49	\$0.10	\$0.15	\$0.74						<u> </u>							1	
	UPPER DOOR SEAL DOUBLER		Clean	656	<del> </del>	1	\$0.01	\$0.00	\$0.00	\$0.02				1							1			
			Part Marking	87	1	1	\$0.10	\$0.02	\$0.03	\$0.15			l			1							1	
11 -		1	INS	146		1	\$0.06	\$0.01	\$0.02	\$0.09						1	<b> </b>			1			1	
-		1			l	1									<b></b>		1			<u> </u>	1			
-		<del> </del>		†	<b></b>	-	ļ —			<b></b>				1		<b> </b>	1						1:	
		1	Total Cost	†	\$0.64	1				\$2.87	\$1.54	\$0.39	\$-	\$	\$-	\$0:56	\$3.12	\$0.16	\$6.14	\$0.61	\$0.61	\$7.37		
	XRS02057-7010	В	LASER	8	\$0.64	1	\$1.10	\$0.22	\$0.33	\$1.65	\$1.54	\$0.39	\$-	\$-	\$-	\$0.56	<del> </del>	<del> </del>			+	T	<del></del>	QTY : 51 onwards
<b>-</b>		+-	FILE	18	+	1	\$0.49	\$0.10	\$0.15	\$0.73	<b>4</b>		<del>                                     </del>	<del>                                     </del>	<u> </u>	1	<del>                                     </del>	-		1	1	1	Ì	
	UPPER DOOR SEAL DOUBLER	-	Clean	656	-	1	\$0.01	\$0.00	\$0.00	\$0.02				<u> </u>		<del> </del>	1	1	<u> </u>	1				
H	*****	-	Part Marking	87	<del> </del>	1	\$0.10	\$0.02	\$0.03	\$0.15			<b></b>			<u> </u>	<del>                                     </del>			<b> </b>				
12		1	INS	262	<del>                                     </del>	1	\$0.03	\$0.01	\$0.01	\$0.05				<del> </del>		<del> </del>	<b>†</b>	1	<del>                                     </del>	<b> </b>	1		1	
<b> </b>		1	<u> </u>	+	<del>                                     </del>	1				<del> </del>					<b></b>	<b> </b>		1			+		1	
-		+		<del> </del>	<del> </del>	<del>                                     </del>				<del> </del>							<del>                                     </del>	-	<u> </u>	<del>                                     </del>	1			
-		1 .	Total Cost	†	\$0.64	<del> </del>	<del> </del>		l	\$2.60	\$1.54	\$0.39	· \$-	\$-	\$-	\$0.56	\$3.12	\$0.16	\$5.87	\$0.59	\$0.59	\$7.05	1	

### ARKTECH PHILIPPINES INC.

T 6B.PHASE 1-A FIRST PHILIPPINE INDUSTRIAL PARK, STO. TOMAS, BAT, TEL. 63(43)405-6140~2

# X

			1	<u> </u>	Run Cos	ts Per Hour		8.73	Arktı	ch's Propose	d Costs												
F	First Philippine Industrial Park, Sto. Tomas, Batangas		2			bour per Hour		2.64		ch's Propose													
			3			our per Hour		1.74		ch's Propose													
Т	В		С	D	E	F	G	Н	ı	J	К	L	М	N.	0	Р	Q	R	S	Т	υ	V	
No	Part No		Process	Qty per Hr	Material Cost Per Part	Manning No	Run Cost Per part	Direct labor per part	Indirect Labor Per Part	Total Facility Costs Per Part	Anodising	Priming	Brush finish	Passivatio n	Etching	Packaging material	Material Cost + Finishing Cost	Overhead Uplift (Material, Processing & Finishing Costs) 5%	(Material + Finishing Cost)+ (Overhead Uplift)+(Total Facility Costs)	General Overhead Uplift 10%	Profit Uplift 10%	Total Part cost	Condition and Remarks
	XRS02057-7011	В	LASER	2	\$0.64	1	\$4.37	\$0.87	\$1.32	\$6.57	\$1.57	\$0.39	\$-	\$-	\$-	\$0.55							QTY:1-2
	UPPER DOOR SEAL DOUBLER 1.5	_	FILE	18		1	\$0.49	\$0.10	\$0.15	\$0.73									-				
	THK		Clean	656	,	1	\$0.01	\$0.00	\$0.00	\$0.02													
H			Part Marking	87		1	\$0.10	\$0.02	\$0.03	\$0.15		-											
-		<b>-</b> `-	INS	6		1	\$1.54	\$0.31	\$0.47	\$2.31													
H								-	<b></b>														
H						<u> </u>			<b></b>					<u> </u>									
H			Tetal Cost		\$0.64		<b> </b>			\$9.78	\$1,57	\$0.39	\$-	\$-	\$-	\$0.55	\$3.16	\$0.16	\$13.10	\$1,31	\$1,31	\$15.72	
			Total Cost					L	<u> </u>					<b> </b>			\$3.10	\$0.10	\$10.10	\$1,01	#1,01	φ10.12	OTV:3 E
L	XRS02057-7011	В	LASER	4	\$0.64	1	\$2.40	\$0.48	\$0.73	\$3.60	\$1.57	\$0.39	\$-	\$-	\$-	\$0.55							\ QTY:3-5
	UPPER DOOR SEAL DOUBLER 1.5		FILE	19		1	\$0.47	\$0.09	\$0.14	\$0.70													
L	THK		Clean	656		1	\$0.01	\$0.00	\$0.00	\$0.02													
			Part Marking	87		11	\$0.10	\$0.02	\$0.03	\$0.15													
			INS	17		1	\$0.51	\$0.10	\$0.16	\$0.77													
Γ			Total Cost	Ì	\$0.64					\$5.24	\$1.57	\$0.39	\$-	\$-	\$-	\$0.55	\$3.16	\$0.16	\$8.56	\$0.86	\$0.86	\$10.27	
	XRS02057-7011	В	LASER	5	\$0.64	1	\$1.79	\$0.36	\$0.54	\$2.68	\$1.57	\$0.39	\$-	\$-	\$-	\$0.55							QTY:6-10
H	UPPER DOOR SEAL DOUBLER 1.5	<del>  -</del>	FILE	19		1	\$0.46	\$0.09	\$0.14	\$0.68					<b></b>								
200	THK		Clean	656		1	\$0.01	\$0.00	\$0.00	\$0.02	. *												
-		-	Part Marking	87		1	\$0.10	\$0.02	\$0.03	\$0.15			· · · · ·					<b></b>		1			*
. H			INS	35		1	\$0.25	\$0.05	\$0.08	\$0.38				<del> </del>				<del>                                     </del>			<b></b>		
H			,,,,		<del> </del>	<del>                                     </del>	40.20		1	40.00			-	<del> </del>		<u> </u>					<del> </del>		
-					<del> </del>	<del> </del>		<del> </del>	<del> </del>								<del> </del>			· ·	<del> </del>	<del> </del>	
-		<del>                                     </del>			l	<del> </del>		-					-	<b>-</b>	<b>-</b>	1000	1000	20.15	07.00	40.70	40.70	60.00	
		<u> </u>	Total Cost	ļ	\$0.64	ļ	<u></u>	<u> </u>		\$3.92	\$1.57	\$0.39	\$-	\$-	\$-	\$0.55	\$3.16	\$0.16	\$7.23	\$0.72	\$0.72	\$8.68	
	XRS02057-7011	В	LASER	6	\$0.64	. 1	\$1.43	\$0.29	\$0.43	\$2.15	\$1.57	\$0.39	\$-	\$-	\$-	\$0.55				ļ			QTY:11-25
	UPPER DOOR SEAL DOUBLER 1.5		FILE	20		1	\$0.45	\$0.09	\$0.13	\$0.67						<u> </u>				<u> </u>		ļ	
	тнк		Clean	656		1	\$0.01	\$0.00	\$0.00	\$0.02										1			
ïſ			Part Marking	87		1	\$0.10	\$0.02	\$0.03	\$0.15									``		ļ		
			INS	62		1	\$0.14	\$0.03	\$0.04	\$0.21													,
ı				1																			
1				<b>T</b>		· · · · ·				<u> </u>									1		1		
- L		+	<del> </del>	-	-	+	+	1		\$3.20		<del> </del>	ļ	+	<del></del>	+	<del> </del>	4	+		<del></del>	\$7.82	

	First Philippine Industrial Park, Sto. Tomas.		1		Run Cos	ts Per Hour	•	8.73	Arkte	nch's Propose	d Costs												•
	Batangas		2		Indirect La	bour per Hour		2.64	Arkte	rch's Propose	d Costs												
			3			our per Hour		1,74	. Arkte	ch's Propose	d Costs						r					·	
_	В		C	D	E	F	G	Н	1	J	K	· 1L	M	N	0	Р	.Q	R	S	т	U	V	
No	Part No		Process	Qty per Hr	Material Cost Per Part	Manning No	Run Cost Per part	Direct labor per part	indirect Labor Per Part	Total Facility Costs Per Part	Anodising	Priming	Brush finish	Passivatio n	Etching	Packaging material	Material Cost + Finishing Cost	Overhead Uplift (Material, Processing & Finishing Costs) 5%	(Material + Finishing Cost)+ (Overhead Uplift)+(Total Facility Costs)	General Overhead Uplift 10%	Profit Uplift 10%	Total Part cost	Condition and Remarks
	XRS02057-7011	В	LASER	8	\$0.64	1	\$1.14	\$0.23	\$0.35	\$1.71	\$1.57	\$0.39	\$-	\$-	\$-	\$0.55							QTY:26-50
Ī	UPPER DOOR SEAL DOUBLER 1.5		FILE	20		1	\$0.44	\$0.09	\$0.13	\$0.66 .		**											
	тнк		Clean	656		1	\$0.01	\$0.00	. \$0.00	\$0.02													
			Part Marking	87		1	\$0.10	\$0.02	\$0.03	\$0.15													· · · · · · · · · · · · · · · · · · ·
			INS	146		11	\$0.06	\$0.01	\$0.02	\$0.09													
1			<del>,</del>			ļ								<u> </u>									
1														ļ									
			Total Cost		\$0.64					\$2,63	.\$1.57	\$0.39	\$-	\$-	\$-	\$0.55	\$3.16	\$0.16	\$5.95	\$0.59	\$0.59	\$7.14	
	· XRS02057-7011	В	LASER	9	\$0.64	1	\$0.99	\$0.20	\$0.30	\$1.49	\$1.57	\$0.39	\$-	\$-	\$-	\$0.55							QTY :51 onwards
	UPPER DOOR SEAL DOUBLER 1.5		FILE	20		1	\$0.43	\$0.09	\$0.13	\$0.65					•								
l	THK ·		Clean	656		1	\$0.01	\$0.00	\$0.00	\$0.02										·			
1			Part Marking	87		1	\$0.10	\$0.02	\$0.03	\$0.15							ļ						
1			INS	262	<u> </u>	1	\$0.03	\$0.01	\$0.01	\$0.05	···												
				ļ	<u> </u>	ļ								ļ.,							ļ	-	
				<b> </b>		ļ .					,	·		ļ		ļ						00.04	
			Total Cost		\$0.64	`				\$2.36	\$1.57	\$0.39	\$-	\$-1	\$-	\$0.55	\$3.16	\$0.16	\$5.67	\$0.57	\$0.57	\$6.81	

(	(crow 9/22/21	CHECKED BY:	APPROVED BY: for practing 9/12 CON	FORME:
/	JESSICA ABAYON	CHRISTINE JANE OLEA	HIDEHIKO ARAKAWA	