

Shop Floor Observation

Operators reported machine jams during high-volume production.

Line stoppages occurred multiple times during the afternoon shift.

Operators stated that machines frequently stop for minor adjustments.