Table 1. Standard ranges of physical parameters within poultry farm [5].

Physical parameters	First week	Second week	Third week	Fourth week
Temperature Relative	34-32 °C	32–30 °C	30–28 °C	29–27 °C
humidity	80-60%	80-60%	80-60%	80-60%
Carbon	Must be 0	.10		
monoxide Carbon	ppm	<10 ppm	<25 ppm	<50 ppm
dioxide Ammonia	<1,000 ppm	<2,000 ppm	<2,500 ppm	<2,500 ppm
level	Near to 0 ppm	<10 ppm	<20 ppm	<25 ppm
Oxygen level	16–18%	16–18%	16–18%	16–19%