1. Description


1.1. Project

Project Name	11_PWM
Board Name	11_PWM
Generated with:	STM32CubeMX 4.22.0
Date	01/28/2018

1.2. MCU

MCU Series	STM32F0
MCU Line	STM32F0x0 Value Line
MCU name	STM32F030F4Px
MCU Package	TSSOP20
MCU Pin number	20


2. Pinout Configuration



3. Pins Configuration

1					
	Pin Number TSSOP20	Pin Name (function after reset)	Pin Type	Alternate Function(s)	Label
	1	воото	Boot		
	4	NRST	Reset		
	5	VDDA	Power		
	8	PA2	I/O	USART1_TX	
	12	PA6	I/O	TIM3_CH1	
	15	VSS	Power		
	16	VDD	Power		
	19	PA13	I/O	SYS_SWDIO	
	20	PA14	I/O	SYS_SWCLK	

4. Clock Tree Configuration



5. IPs and Middleware Configuration

5.1. SYS

mode: Debug Serial Wire Timebase Source: SysTick

5.2. TIM3

mode: Clock Source

Channel1: PWM Generation CH1

5.2.1. Parameter Settings:

Counter Settings:

Prescaler (PSC - 16 bits value)

Counter Mode

Counter Period (AutoReload Register - 16 bits value)

Internal Clock Division (CKD)

auto-reload preload

24 *

Up

200 *

No Division

Disable

Trigger Output (TRGO) Parameters:

Master/Slave Mode Disable (no sync between this TIM (Master) and its Slaves

Trigger Event Selection Reset (UG bit from TIMx_EGR)

PWM Generation Channel 1:

Mode PWM mode 1

Pulse (16 bits value) 0
Fast Mode Disable
CH Polarity High

5.3. USART1

Mode: Single Wire (Half-Duplex)

5.3.1. Parameter Settings:

Basic Parameters:

Baud Rate 38400

Word Length 8 Bits (including Parity)

Parity None Stop Bits 1

Advanced Parameters:

Data Direction Receive and Transmit

Over Sampling 16 Samples
Single Sample Disable

Advanced Features:

Auto Baudrate Disable Disable TX Pin Active Level Inversion RX Pin Active Level Inversion Disable Data Inversion Disable Disable TX and RX Pins Swapping Overrun Enable DMA on RX Error Enable MSB First Disable

* User modified value

6. System Configuration

6.1. GPIO configuration

IP	Pin	Signal	GPIO mode	GPIO pull/up pull down	Max Speed	User Label
SYS	PA13	SYS SWDIO	n/a	n/a	n/a	
	PA14	SYS_SWCLK	n/a	n/a	n/a	
TIM3	PA6	TIM3_CH1	Alternate Function Push Pull	No pull-up and no pull-down	Low	
USART1	PA2	USART1_TX	Alternate Function Open	Pull-up	High *	
			Drain	•		

6.2. DMA configuration

nothing configured in DMA service

6.3. NVIC configuration

Interrupt Table	Enable	Preenmption Priority	SubPriority
Non maskable interrupt	true	0	0
Hard fault interrupt	true	0	0
System service call via SWI instruction	true	0	0
Pendable request for system service	true	0	0
System tick timer	true	0	0
Flash global interrupt	unused		
RCC global interrupt	unused		
TIM3 global interrupt	unused		
USART1 global interrupt	unused		

^{*} User modified value

7. Power Consumption Calculator report

7.1. Microcontroller Selection

Series	STM32F0
Line	STM32F0x0 Value Line
мси	STM32F030F4Px
Datasheet	024849_Rev2

7.2. Parameter Selection

Temperature	25
IVAA	3.6

8. Software Project

8.1. Project Settings

Name	Value
Project Name	11_PWM
Project Folder	C:\Users\armst\Desktop\STM32\STM32F030F4P6\GCC\11_PWM
Toolchain / IDE	TrueSTUDIO
Firmware Package Name and Version	STM32Cube FW_F0 V1.8.0

8.2. Code Generation Settings

Name	Value
STM32Cube Firmware Library Package	Copy only the necessary library files
Generate peripheral initialization as a pair of '.c/.h' files	No
Backup previously generated files when re-generating	No
Delete previously generated files when not re-generated	Yes
Set all free pins as analog (to optimize the power	No
consumption)	