

Licensing Conditions for establishing a New Ginning Mill

- Installation of special equipment for treating seeds and dust with heat suitable for processing seeds produced from all ginning machines immediately after extraction from cotton.
- Attachments for these devices mounted on the steam pipe feeding the treatment unit, including: (valve – pressure reducing valve – safety valve – automatic regulator – manometer – daily recorder – exhaust box).
- Steam generator to supply the treatment equipment.
- Mechanized lifts and conveyors to transfer seeds directly from the ginning machines to the seed treatment equipment.
- Establishment of a chamber for destroying waste that cannot be separated from seeds, on the same day of production, in compliance with environmental standards.

Additional Requirements for Mills Producing Seed for Planting

- An additional treatment device for processing seeds resulting from *escarto* (by-products).
- A seed cleaning machine (separator) with units and sizes appropriate to the quantity of seeds produced during the operation of all ginning machines.
- The mill yards must be spacious enough to store seed for planting and commercial seed, as well as approximately one-quarter of the cotton (unginned and lint) expected to be processed during the ginning season.
- Prepare an office for the agricultural engineer to oversee operations.

Required Documents for Licensing a New Ginning Mill

- Ownership or lease contract for the land on which the mill is established.
- Tax card indicating the activity (Cotton Ginning).
- Commercial register indicating the activity (Cotton Ginning).
- Approval from the Ministry of Environment.
- Approval from Industrial Safety Authority.
- Approval from Civil Protection Authority.
- Approval from the Industrial Development Authority.
- Construction and occupancy permit from the competent authority.
- Local unit license indicating the activity (Cotton Ginning).
- Approved engineering drawings showing all equipment and facilities of the mill.
- Inspection report and site sketch consistent with the engineering drawings.
- Receipt of payment for inspection fees and required stamps.
- Application submitted by the company responsible for managing the mill at least one month before operation, bearing the required stamp duty.

Procedures for Renewing the Operating License of an Existing Ginning Mill.”

1. The company must submit a renewal request before the license expires, during July, with the required stamp duties.
2. Pay renewal fees
3. An inspection report must cover all ginning equipment and facilities, specifying the number of regular, escarto, sample, and zero ginning machines.
4. Submit a report confirming that no changes occurred in the equipment, or detailing any modifications made.
5. Ensure the commercial register and tax card are valid and updated to reflect the activity.
6. Approvals from Industrial Safety and Civil Defense authorities.
7. Obtain environmental approval

Required Documents for Renewal of Operating License

- Copy of ownership or lease contract.
- Copy of boiler or steam generator license (valid).
- Receipt of payment for renewal fees.
- Renewal application form.
- Copy of tax card.
- Copy of commercial register.
- Copy of approval from Industrial Safety and Civil Defense authorities.
- Copy of approval from the Ministry of Environment.

Conditions and Documents for Licensing a Zero Roller (Doulab El-Zero)

First: Licensing Conditions

1. It must be located in the seed hall next to the *escarto* rollers.
2. An automatic feeding connection must be installed to deliver the seed directly to the fumigation chamber to ensure proper treatment.

Second: Licensing Documents

1. Inspection report of the roller site and the automatic seed feeding connection to the fumigation chamber.
2. Site sketch (layout drawing).
3. Payment of the prescribed inspection fees.
4. Licensing application (Form No. 17).

“Conditions and Procedures for Licensing an External Depot for Storing Seed Cotton and Ginning By-products, in accordance with Article (16) of Ministerial Decree No. 88 of 1967 implementing Article 34(c) of Law No. 53 of 1966.”

Conditions and Required Documents for Licensing an External Depot for Storing Seed Cotton and Ginning By-products

First: Licensing Conditions

1. It must not be more than 5 km away from the ginning mill and should be located within the jurisdiction of the district.
2. It must have an external fence, a gate, and a room for the responsible worker.
3. Records must be maintained to register incoming seed cotton and outgoing quantities.
4. It must contain a sufficient number of wooden pallets required for stacking seed cotton.
5. Firefighting facilities must be available, such as hydrants or barrels filled with water.

Second: Required Documents for Licensing an External Depot

1. Lease or ownership contract of the depot.
2. Site sketch showing the location of the depot and its boundaries in different directions.
3. Inspection report of the depot prepared by the mill's inspection engineer, indicating its location, area, dimensions, and compliance with the required conditions.
4. Stamped application form from the mill manager regarding the licensing of an external depot.
5. Payment of inspection fees after verifying compliance with the conditions and required stamps.
6. Approval from the Land Protection Authority, if possible.
7. Submission of these documents to the Seed Testing and Certification Department in the governorate, which will then forward them to the General Administration for Gins and Oil Mills.