


A shared plan. A visible route. A human decision.

MUSTER / TRAINING DRAWING / F07

Studio → Stair B

UNAVAILABLE — rejected by the Stair B scenario condition · diagram 14 m · authored route 18 m



E Extinguisher · H Hose reel · M Manual call point · P Assistance holding-point fixture
MX-FS-07-004 / Rev 04 · dimensions from fictional drawing · doors and route geometry inferred

NOT AN APPROVED ESCAPE PLAN. DO NOT DISPLAY AS EMERGENCY SIGNAGE.

Numbers match the walkthrough. A line to a stair is not proof of a safe onward route or successful evacuation.

01 Locate Studio

6 registered in this zone; 2 assistance flags. These are fixture counts, not live occupancy.

02 Check the doorway

The opening is inferred from the training drawing. Confirm the actual approved layout before using any real plan.

03 Review the corridor

This line illustrates a corridor connection, not smoke tenability, congestion or a validated accessible path.

04 Stop: unavailable Stair B

The Stair B inject removes this candidate. Playback stops; compare Stair A without treating it as a safety guarantee.

05 Hand off and account

The model ends at this stair landing, not a place of safety. Confirm onward movement, assistance ownership and assembly accounting in the approved plan.

Two assistance flags remain without a recorded assistance owner. Do not mark them accounted for from this preview.

Facilitator / plan reviewer / date

Stair B is unavailable in the current scripted scenario. 14 m is the illustrated polyline; 18 m is the separate authored fixture distance. Neither is a verified real-world evacuation distance. Preview does not record an action.

People, responsibilities and the rehearsal record.

84

FICTIONAL REGISTER · NOT LIVE

Who is responsible?

ROLE	NAMED EXERCISE OWNER	CHECK
Fire Safety Manager	A. Rahman	☐ Confirm
Chief Security	Mei Lin	☐ Confirm
East Fire Warden	D. Kumar	☐ Confirm
West Fire Warden	S. Tan	☐ Confirm
Mobility assistance	UNASSIGNED	☐ Confirm

Assistance details, individual consent, appropriate equipment and backup coverage require a qualified person. No medical capability is inferred.

What does the plan actually show?

ITEM	LOCATION / INVENTORY ID	CHECK
E · Extinguisher	Meeting suite threshold EX-07-W1	☐ Inspect
H · Hose reel	East corridor HR-07-E1	☐ Inspect
M · Manual call point	Lift lobby west MCP-07-L1	☐ Inspect
P · PWD holding point	Studio smoke-stop approach PWD-07-S1	☐ Inspect

The detector signal is scripted near 7-E. Equipment symbols do not establish serviceability, adequacy or permission to operate equipment.

Account for people, not just actions.

ZONE	REGISTER	ASSISTANCE	OBSERVED AT ASSEMBLY
West workplace	29	0	____ / not verified
East workplace	39	0	____ / not verified
Meeting suite	8	0	____ / not verified
Studio	6	2	____ / not verified
Lift lobby	2	0	____ / not verified
Electrical room 7-E	0	0	____ / not verified

2

ACTIVE EVENTS WITHOUT A RESPONSE

The decision in four checks

OBSERVE
Studio: 6 fixture occupants, 2 need assistance.
CONSTRAINT
Stair B is unavailable because the facilitator introduced that condition.
COMPARE
Reject Stair B in this exercise. The drawn line is 14 m; the separate authored distance is 18 m.

HUMAN CHECK

Verify the approved route, who helps whom and assembly accounting. A preview records no team action.

Run the tabletop, then review it.

- ☐ Confirm the approved plan revision and exercise scope.
- ☐ Confirm the facilitator, wardens, security lead, CERT lead, and assistance owners.
- ☐ Confirm observers know this is a drill and know how to stop the exercise.
- ☐ Introduce one scripted event. Ask each owner to state the intended response; record only what was observed.
- ☐ Reconcile the people register at the designated assembly location in the approved plan.
- ☐ Debrief gaps. Assign an improvement owner, due date and closure evidence. Keep final approval human.

Snapshot, not a completion claim

Events: Detector activation · Stair B unavailable

Recorded actions: None

Unresolved: Floor 7 accounting has no recorded owner. · No alternate route recorded for Stair B.

Observed issue / improvement owner / due date

Planning context: SCDF Emergency Response Plan resources, scdf.gov.sg/fire-safety-services-listing/emergency-response-plan. Muster is not affiliated with SCDF and this pack is not an approved ERP. 3D height, openings, furniture and route geometry are inferred from a fictional drawing.