
8. What kind of stress does this graph show?



- a) Reversed stress
- b) Fluctuating stress
- c) Irregular stress
- d) Constant stress
- 9. Fatigue of materials is characterized by \_\_\_\_\_ curve.
- a) Hermite
- b) Bezier
- c) Wohner
- d) S-T
- 10. How can the mean stress of fatigue be evaluated?
- a) Pascal's equation
- b) Soderberg equation
- c) Heisenberg's equation
- d) Goodman relation
- 11. The stress below which the material does not fail is called \_\_\_\_\_
- a) Fatigue stress
- b) Endurance limit
- c) Fatigue life
- d) Total stress