

Service Training and Quality Parameters mapped on Dashboard

- 1. Technician Strength
- 2. Experience Profile
- 3. Star Rating
- 4. Training Mandays
- 5. CSAT Survey Reports
- 6. PRA
- 7. FTF
- 8. Spare Replaced
- 9. Monthly Repeat
- 10. Annual Repeat


1. Technician Strength




2. Technician Experience Profile




3. Star Rating




4. Mandays



5. CSAT Survey Report




6.1 PRA Status




Branch can easily monitor PRA limit consumed, Proportion of Damage vs Defective and Refund Indication

11. Monthly Repeat




Monthly Repeat Performance can be monitored and analysed for Normal and RDC calls in One Page.

12.1 Annual Repeat – Zone and Branch Wise



12.3 Annual Repeat – Technician Wise




12.4 Annual Repeat – Technician Wise - Call Details

Franchisee Id Installation	Job Category	1	Job Category 2		Job Category 3		Service Order Number	Technician Id	Branch	Zone Repeat Co	unt
3HX000702 RD0524445045004447 400704447	4434 LIGHT	.cD	LIGHT P	JSED	SPAP	CD?	178474	804943	MUMBAI	West	2
3HX000702 /	THEF		KNOB -	ICORRECT	CUS	CATION	102410	804943	MUMBAI	West	2
3HX000702	LIGH	D	BULB/LI	ROKEN	REFI'		152999	804943	MUMBAI	West	1
3HX000702	MAII		GASKET	:D	REFI'		142032	804943	MUMBAI	West	1
3HX000702	THE		EXCESS		SPAF	D	105709	804943	MUMBAI	West	-1
3HX000702	LOO	TION	BULB H		REFI'		115800	804943	MUMBAI	West	-1
3HX000702	WAT	E/SWEATING	SWEATI	DOOR	REFI'		152264	804943	MUMBAI	West	2
3HX000702	MAII		GASKET		REFI'		218410	804943	MUMBAI	West	-1
3HX000702	CABI		LEVELLI		LEVE	E	171199	804943	MUMBAI	West	1
3HX000702	CAB		APRON	ICIA (NON MUT) BROKEN - IN TRANSIT	SPAF	0	180849	804943	MUMBAI	West	2
3HX000702	FREE		LOCK B	SOKEN	SPAF	D	212943	804943	MUMBAI	West	1
3HX000702	MAII		GASKET		REFI'		229964	804943	MUMBAI		1
3HX000702 RL	LIGH	D	LIGHT E	JSED	SPAF	ED	113138	804943	MUMBAI		1
dina Daga fan Duill Hanavala	00264 THEF		EXCESS		SPAF	D	171031	804943	MUMBAI		1
ding Page for Drill through	00903 CON)	MAIN P	RATIC MAIN PCB	SPAF	D	255294	804943	MUMBAI		2
T ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	01102 FREE		DOOR ·	/DENTS & SCRATCHES	SPAF	D	214608	804943	MUMBAI		1
Technician Wise.	3336 FREE		DOOR ·	/DENTS & SCRATCHES	SPAF	0	258204	804943	MUMBAI		2
21.0000703	3336 MAII		DOOR ·	ED IN-TRANSIT	ADJU	ITTED	228040	804943	MUMBAI		2
3HX000702	LIGH	D	LIGHT E	JSED	SPAF	ED	228526	804943	MUMBAI		1
3HX000702 3HX000702	LIGH	(FF MANUAL)	LIGHT E STICKY	DLDER DEFECTIVE ING	REFI' SPAF	D	203171 126662	804943 804943	MUMBAI MUMBAI		1
310/000702	Sens Sens	(FF MANUAL)	NOT W	ING	SPAF	0	117759	804943	MUMBAI		2
eta e a companio de la companio della companio dell	MAI		DOOR -	ED IN-TRANSIT	ADJU	ITTED	183563	804943	MUMBAI		1
This will help branch to	DEF	(FF MANUAL)		ING	SPAF	D	135163	804943	MUMBAI		1
·	DEF	(FF MANUAL)	STICKY	ING	SPAF	5	229102	804943	MUMBAI		÷
nalyse cause of repeat and	MAII	(IT INDITALITY)	DOOR -	ED IN-TRANSIT	ADJU	ITTED	173807	804943	MUMBAI		1
•	AIR	TI FLOW DUCT)		SPOILED	REFI	11120	187108	804943	MUMBAI		÷
iron out issues	AIR	TI FLOW DUCT)		J DUCT (FF)	REFI	VED	114773	804943	MUMBAI		1
2121220122 1117	DEF	(FF MANUAL)		ING	SPAF	D	239211	804943	MUMBAI		1
3HX000702	MAI		GASKET		REFI'		182217	804943	MUMBAI		1
3HX000702	CON		NOISE -	- ABNORMAL	CUS	IVINCED	216846	804943	MUMBAI		1
3HX000702	AIR I	TI FLOW DUCT)	MULTIF	MISALGINED	REFI'	ED FOAM	197006	804943	MUMBAI	West	2
3HX000702	THE		EXCESS		SPAF	D	214908	804943	MUMBAI	West	2
3HX000702	AIR	TI FLOW DUCT)	NO AIR	J DUCT (FF)	REFI'	VED	173924	804943	MUMBAI	West	2
3HX000702	THE		EXCESS		SPAF	D	215030	804943	MUMBAI	West	2
3HX000702	DEF	(FF MANUAL)	STICKY	ING	SPAF	0	207075	804943	MUMBAI	West	2
3HX000702	MAII		GASKET		REFI'		203763	804943	MUMBAI	West	1
3HX000702	MAII		DOOR -	ED IN-TRANSIT	ADJU	ITTED	113960	804943	MUMBAI	West	1
3HX000702	MAII		DOOR -	ID .	REAL		242905	804943	MUMBAI	West	2
3HX000702	MAII		DOOR -	ED IN-TRANSIT	ADJL	ITTED	247068	804943	MUMBAI	West	2
3HX000702	COMPRESSOR		NOISE - RUNNIN	IG - ABNORMAI	CUSTOMER CO	NVINCED	173741	804943	MUMBAL	West	- 2

Internal


Unique things about this dashboard

Recognition of Month as per Financial Year




Power BI sorts month as per Calendar year. Logic developed to sort the same as per Financial Year

Multiple cross report and those visualization linkages enabling useful insights




Manual data cleansing and calculation steps are mapped in Power Query



This helps avoid redundancy of the same upon updation

Filters at Dax Level instead of usual Visual or Page Level



This allows to free other variables of the calculation from these filters thereby allowing complex calculation automated. In absence of this many manual steps may have been added rendering the updation of parameter cumbersome and time taking.

Last Source File Updation Date displayed on Dashboard Page

