



(An ISO 9001:2015, ISO 14001:2015 & ISO 45001:2018 Certified Company)



Comprehensive Multi-Audit Report

Section - I: Power Supply System

Section - II: Electrical Panels & Distribution Boards

Power Supply System | Electrical Panels & Distribution Boards

Conducted for



At: Techxpert-Noida

Sol ID: 001

State/UT: DELHI

Audit Work Conducted on **July 7, 2026**



By

Techxpert Facilities India Private Limited

451 - 452, First Floor, Leela Ram Market, Masjid Moth, South Extension Part - 2, New Delhi, Delhi -
110049, India

Executive Summary	4
Audit Lifecycle Timeline	4
Audit Analytics and Visual Summary	4
Branch Audit History	5
Non-Conformance Register	5
Power Supply System - Checklist	6
Electrical Panels & Distribution Boards - Checklist	6
Audit Notes and Findings	6
Site Photographs	6
Acknowledgement	7





(An ISO 9001:2015, ISO 14001:2015 & ISO 45001:2018 Certified Company)



Disclaimer:

The findings mentioned in report are based on the data & information collected during Assessment period & recommendations are based on International Standards & Guidelines. Any modification done in the facility after the Assessment period is not covered in the report.





CORPORATE AUDIT BRANCH REPORT

Professional Site Audit & Compliance Assessment
Confidential – For Client Use Only

Report Ref: CS-AUD-000007
Generated: 22-Jul-2026 15:41
Audit Type: Power Supply System


Customer / Site Details		Audit Ticket Details	
Company	: TECHXPERT	Ticket ID	: CS-AUD-000007
Branch	: Techxpert-Noida	Master Audit	: EnergyAudit
Branch Code	: 001	Sub Audit	: Power Supply System
Floor / Level	: ttt	Status	: Completed
Address	: Delhi, TECHXPERT FACILITIES INDIA	Raised On	: 2026-07-07 07:56:40
	PRIVATE LIMITED A-812, TOWER -A 8TH	Completed On	: 2026-07-07 13:28:14
	FLOOR, LOGIX CYBER PARK SECTOR -	Auditor	: Demo (7210720153)
City / State	62, NOIDA UTTAR PRADESH - 201309,	Branch Account	: ADITYA MISHRA (7210720153)
	DELHI, DELHI, 110005	Manager	
		Geo Location	: -
PIN Code	: 110005		
Contact	: 7210720153		
Email	:		
	deepakchauhan7210march@gmail.c		
	om		

Executive Audit Summary					
D AUDIT GRADE Needs Improvement	Critical RISK LEVEL	Improving (+50% vs last audit) TREND VS LAST AUDIT	5.5 hrs TURNAROUND TIME	6 BRANCH AUDITS (ALL)	38.9% BRANCH AVG PASS RATE
Previous Audit at Branch CS-AUD-000002 on 2026-06-25 — Pass Rate: 16.7% Not OK: 5					
Audit Scope		Power Supply System Electrical Panels & Distribution Boards 2 audits on ticket #CS-AUD-000007			


Audit Lifecycle Timeline	
Stage	Date & Time
Raised	2026-07-07 07:56:40
Assigned	2026-07-07 07:56:50
Started	2026-07-07 13:10:26
Completed	2026-07-07 13:28:14
Closed	-

15 TOTAL CHECKPOINTS	10 OK	5 NOT OK	66.7% PASS RATE	40% IN RANGE
--------------------------------	-----------------	--------------------	---------------------------	------------------------

Audit Analytics & Visual Summary



Trend Analysis – Daily & Monthly



Branch Audit History (Last 12 Audits)

Ticket ID	Audit Date	OK	Not OK	Pass Rate	Note
CS-AUD-000007	2026-07-07	10	5	66.7%	Current
CS-AUD-000002	2026-06-25	1	5	16.7%	-
CS-AUD-000001	2026-06-24	2	4	33.3%	-

Non-Conformance Register

#	Checkpoint	Actual Value	Status	Compliance	Remarks / Action
1	MDB/Sub-DB condition satisfactory	No	Not OK	Out of Range	aa
2	Circuit labeling provided and legible	No	Not OK	Out of Range	aaa
3	MCBs/MCCBs in good condition	No	Not OK	Out of Range	aa
4	Busbar insulation satisfactory	aa	Not OK	N/A	aa

#	Checkpoint	Actual Value	Status	Compliance	Remarks / Action
5	Adequate clearance inside panel	No	Not OK	Out of Range	aaa

Power Supply System – Detailed Checklist

EnergyAudit

#	Checkpoint	Ideal	Min	Max	Value	OK / Not OK	Remarks	Compliance	Photo
1	Incoming utility power supply condition checked	-	-	-	Yes	OK	tt	In Range	-
2	DG supply available and functional	-	-	-	Yes	OK	ttt	In Range	-
3	UPS supply available and functional	-	-	-	Yes	OK	tt	In Range	-
4	Metering panel condition satisfactory	-	-	-	Yes	OK	tt	In Range	-
5	Service line condition satisfactory	-	-	-	Yes	OK	tt	In Range	-
6	Connected load within sanctioned load	-	-	-	Yes	OK	ttt	In Range	-

Electrical Panels & Distribution Boards – Detailed Checklist

EnergyAudit

#	Checkpoint	Ideal	Min	Max	Value	OK / Not OK	Remarks	Compliance	Photo
7	LT Panel condition satisfactory	-	-	-	aa	OK	aaa	N/A	
8	MDB/Sub-DB condition satisfactory	-	-	-	No	Not OK	aa	Out of Range	
9	Circuit labeling provided and legible	-	-	-	No	Not OK	aaa	Out of Range	-
10	Panel earthing available	-	-	-	aa	OK	aa	N/A	-
11	Body grounding proper	-	-	-	aa	OK	aa	N/A	-
12	MCBs/MCCBs in good condition	-	-	-	No	Not OK	aa	Out of Range	-
13	RCCB/ELCB functional	-	-	-	aa	OK	aaa	N/A	
14	Busbar insulation satisfactory	-	-	-	aa	Not OK	aa	N/A	
15	Adequate clearance inside panel	-	-	-	No	Not OK	aaa	Out of Range	-

Audit Notes & Findings

Problem Reported by Client	ttt
Observation	ttt
Action Taken	ttt
Conclusion	-
Auditor Notes	-
General Remarks	ttt

Site Photo Evidence (4 attachments)

#7 - LT Panel condition satisfactory

Status:  Value: aa

#8 - MDB/Sub-DB condition satisfactory

Status:  Value: No

#13 - RCCB/ELCB functional

Status:  Value: aa

#14 - Busbar insulation satisfactory

Status:  Value: aa

Authorization & Sign-off

Auditor
Name: Demo
Contact: 7210720153

Signature

Client Representative
Name: ttt
Designation: tt
Contact: tt
Email: deepakchauhan7210march@gmail.com


Client Signature

This is a system-generated audit report prepared by TechXpert Service. The information contained herein is based on on-site inspection data captured via the mobile audit application. Photos are stored securely at admin/media/audit-ticket/.