IoT Environment: Implementing Security Measures

Enhancing IoT Security Through Authentication, Accounting, and Advanced Measurement Tools: A Comprehensive Approach Using Wireshark and BetterCap



IoT Environment: Implementing Security Measures

Mohammed Alramadan muhammedarramadan@gmail.com Mohammed Ali


University of Calabria




IoT Basic Architecture












IoT Basic Architecture: Security Implementation




Monitoring IoT Security









Node Red Architecture



Dashboard Architecture




Maria DB Heidi SQL




Setting up SSL/TLS Communication ESP32

```
Output Serial Monitor x
 Message (Enter to send message to 'ESP32 Wrover Module' on 'COM3')
07:18:39.052 -> [ 2895][V][WiFiGeneric.cpp:355] arduino event cb(): STA Connected: SSID: MUHAMMED97, BSSID: 02:d7:29:ca:e8:35, Channel: 1, Auth: WPA2 PSK
07:18:39.052 -> [ 2897][D][WiFiGeneric.cpp:1035] eventCallback(): Arduino Event: 4 - STA CONNECTED
07:18:39.084 -> [ 2925][V][WiFiGeneric.cpp:369] arduino event cb(): STA Got New IP:192.168.156.31
07:18:39.084 -> [ 2925][D][WiFiGeneric.cpp:1035] eventCallback(): Arduino Event: 7 - STA GOT IP
07:18:39.084 -> [ 2929][D][WiFiGeneric.cpp:1098] eventCallback(): STA IP: 192.168.156.31, MASK: 255.255.255.0, GW: 192.168.156.62
07:18:41.369 -> Free Heap: 214636
07:18:41.402 -> [ 5235][V][ssl client.cpp:62] start ssl client(): Free internal heap before TLS 214636
07:18:41.402 -> [ 5235][V][ssl client.cpp:68] start ssl client(): Starting socket
07:19:04.257 -> [ 28089][V][ssl client.cpp:146] start ssl client(): Seeding the random number generator
07:19:04.257 -> [ 28090][V][ssl client.cpp:155] start ssl client(): Setting up the SSL/TLS structure...
07:19:04.257 -> [ 28094][V][ssl client.cpp:178] start ssl client(): Loading CA cert
07:19:04.257 -> [ 28102][V][ssl client.cpp:234] start ssl client(): Loading CRT cert
07:19:04.303 -> [ 28108][V][ssl client.cpp:243] start ssl client(): Loading private key
07:19:04.303 -> [ 28113][V][ssl client.cpp:254] start ssl client(): Setting hostname for TLS session...
07:19:04.303 -> [ 28120][V][ssl client.cpp:269] start ssl client(): Performing the SSL/TLS handshake...
07:19:05.952 -> [ 29779][D][ssl client.cpp:282] start ssl client(): Protocol is TLSv1.2 Ciphersuite is TLS-ECDHE-ECDSA-WITH-AES-256-GCM-SHA384
07:19:05.952 -> [ 29779][D][ssl client.cpp:284] start ssl client(): Record expansion is 29
07:19:05.952 -> [ 29786][V][ssl client.cpp:290] start ssl client(): Verifying peer X.509 certificate...
07:19:05.952 -> [ 29793][V][ssl client.cpp:298] start ssl client(): Certificate verified.
07:19:05.983 -> [ 29800][V][ssl client.cpp:313] start ssl client(): Free internal heap after TLS 175784
07:19:05.983 -> [ 29808][V][ssl client.cpp:369] send ssl data(): Writing HTTP request with 47 bytes...
07:19:05.983 -> MQTT Communication has been successfully established
07:19:05.983 -> [ 29831][V][ssl client.cpp:369] send ssl data(): Writing HTTP request with 39 bytes...
07:19:06.020 -> [ 29834][V][ssl client.cpp:369] send ssl data(): Writing HTTP request with 42 bytes...
07:19:08.013 -> Free Heap: 175768
```

Setting up SSL/TLS Communication For the Web Server




Setting up Accounting For the Web Server




Connecting to the Web Server

```
○ Administrator: Windows Powe × + ∨
2024-01-25 12:36:26,502 [INFO] - Received credentials - Username: mo, Password: 1234543210
Authorization Accepted for Downloading only ...
Account mo accepted
192.168.156.226 - - [25/Jan/2024 12:36:26] "GET /report.csv HTTP/1.1" 200 -
192.168.156.226 - - [25/Jan/2024 12:36:26] "GET /report.csv HTTP/1.1" 200 -
2024-01-25 12:36:26,933 [INFO] - Received GET request: /favicon.ico
2024-01-25 12:36:26,933 [INFO] - Received credentials - Username: mo, Password: 1234543210
2024-01-25 12:36:26,933 [WARNING] - Authorization not accepted
192.168.156.226 - - [25/Jan/2024 12:36:26] "GET /favicon.ico HTTP/1.1" 401 -
2024-01-25 12:38:03,895 [INFO] - Received GET request: /report.csv
2024-01-25 12:38:03,896 [WARNING] - No Authorization header received
192.168.156.226 - - [25/Jan/2024 12:38:03] "GET /report.csv HTTP/1.1" 401 -
2024-01-25 12:38:52,028 [INFO] - Received GET request: /report.csv
2024-01-25 12:38:52,028 [INFO] - Received credentials - Username: root, Password: 1234543210
Authorization Accepted for Root User ...
Account root accepted
192.168.156.226 - - [25/Jan/2024 12:38:52] "GET /report.csv HTTP/1.1" 200 -
192.168.156.226 - - [25/Jan/2024 12:38:52] "GET /report.csv HTTP/1.1" 200 -
2024-01-25 12:38:52,463 [INFO] - Received GET request: /favicon.ico
2024-01-25 12:38:52,463 [INFO] - Received credentials - Username: root, Password: 1234543210
Authorization Accepted for Root User ...
Account root accepted
192.168.156.226 - - [25/Jan/2024 12:38:52] "GET /favicon.ico HTTP/1.1" 200 -
192.168.156.226 - - [25/Jan/2024 12:38:52] code 404, message File not found
192.168.156.226 - - [25/Jan/2024 12:38:52] "GET /favicon.ico HTTP/1.1" 404 -
```



Confirming CSP Work


Preventing XSS Attack



IoT Architecture (with Bluetooth)








IoT Architecture (with Bluetooth)















Setting Bluetooth Communi ESP32



Setting Bluetooth Communic ESP32





Handles	Service > Characteristics input dat	Properties	mperature: 20.2Data		
0001 → 0005 0003	Generic Attribute (1801) Service Changed (2a05)	INDICATE	imidity: 10%		
0014 → 001c 0016 0018 001a	Generic Access (1800) Device Name (2a00) Appearance (2a01) 2aa6	READ READ READ	Long name works now Unknown 00		
0028 → ffff 002a	4fafc2011fb5459e8fccc5c9c331914b beb5483e36e14688b7f5ea07361b26a8	READ, WRITE, NOTIFY	Temperature: 20.2°C 0a Humidity: 39.6%		

```
0.2.0/24 > 10.0.2.15 » ble.write 24:0a:c4:ef:66:0a beb5483e36e14688b7f5ea07361b26a8 "54656d70657261747572653a20323030c3b0430a48756d69646
974793a203339302e3625"
```

[20:21:39] [sys.log] [inf] ble.recon connecting to 24:0a:c4:ef:66:0a ... 10.0.2.0/24 > 10.0.2.15 »



File Actions Edit View Help

10.0.2.0/24 > 10.0.2.15 » ble.write 24:0a:c4:ef:66:0a beb5483e36e14688b7f5ea07361b26a8 "54656d70657261747572653a20323030c3b0430a48756d69646 974793a203339302e3625"

	L Convers			
Handles	Service > Characteristics	Properties	Data	
0001 → 0005 0003	Generic Attribute (1801) Service Changed (2a05)	INDICATE	1 48 75 6d 69 64 69 74 79 3a 20 31 3	
0014 → 001c 0016 0018 001a	Generic Access (1800) Device Name (2a00) Appearance (2a01) 2aa6	READ READ READ	Long name works now Unknown 00	
0028 → ffff 002a	4fafc2011fb5459e8fccc5c9c331914b beb5483e36e14688b7f5ea07361b26a8	READ, WRITE, NOTIFY	Temperature: 200ðC 0a Humidity: 390.6%	



01:50:44.166 -> 200.00

01:50:44.166 -> 390.60

01:50:44.295 -> 200.00

01:50:44.295 -> 390.60

01:50:44.391 -> 200.00

01:50:44.391 -> 390.60

01:50:44.488 -> 20.20

01:50:44.488 -> 39.60

Setting Bluetooth Communication ESP32

Preventing MITM Attack

```
33
                                                                                  HUMIDITY_CHARACTERISTIC_OULD,
                                                                                   BLECharacteristi :: PROPERTY READ
BLE_client | Arduino IDE 2.2.1
File Edit Sketch Tools Help
                                                                                                 ();
                                                                                       V .O∵
                    ESP32 Wrover Module
                                                                                                 pAdvertising = BLEDevice::getAdvertising();
                                                                                             ... ddServiceUUID(pService->getUUID());
      BLE_client.ino
                                                                                               ==etScanResponse(true);
              #include <NimBLEDevice.h>
                                                                                                 tAdvertising();
              #include <NimBLEClient.h>
              #define SERVER_ADDRESS "7C:9E:BD:66:56:8E"
              #define SERVICE UUID "4tal 201_1fb5_450c-8fcc-c5c9c331914b"
              #define TEMPERATURE CHARACTERISTIC UUID "beb5483e-36e1-4688-b7f5-ea07361b26a9"
              #define HUMIDITY_CHARACTERISTIC_UUID "beb5483e-36e1-4688-b7f5-ea07361b26aa"
                                                                                                 re = dht.readTemperature();
              #include <WiFi.h>
                                                                                                 = dht.readHumidity();
              #include <PubSubClient.h>
              #include <WiFiClientSecure.h>
                                                                                                 naracteristics with the latest values
                                                                                                                         Ln 33, Col 34 ESP32 Dev Module on COM3 Q
```

);

BLE_server | Arduino IDE 2.2.1

File Edit Sketch Tools Help

BLE server.ino

ESP32 Dev Module

BLEDevice::init("BLE Server");

pServer = BLEDevice::createServer();

TEMPERATURE_CHARACTERISTIC_UUID,
BLECharacteristic::PROPERTY READ

BLEService* pService = pServer->createService(SERVICE UUID);


pTemperatureCharacteristic = pService->createCharacteristic(

pHumidityCharacteristic = pService->createCharacteristic(

```
## Discretize ## Discreti
```

RSSI .	MAC	Name	Vendor	Flags	Connect	Seen
-48 dBm -73 dBm -74 dBm -76 dBm -77 dBm -89 dBm	24:0a:c4:ef:66:0a c1:84:66:86:c1:18 bf:ba:cd:df:64:a6 6d:27:87:9f:75:8e 62:c1:cc:fd:ad:0c 7d:67:a9:05:13:6a	Long name works now	Espressif Inc. Apple, Inc. Apple, Inc. Apple, Inc. Microsoft	BR/EDR Not Supported Limited Discoverable, BR/EDR Not Supported LE + BR/EDR (controller), LE + BR/EDR (host) LE + BR/EDR (controller), LE + BR/EDR (host)	* * * * * * * * * * * * * * * * * * *	20:27:37 20:27:37 20:27:37 20:27:37 20:27:37 20:27:34

Handles	Service > Characteristics	Properties	Data		
0001 → 00 0003	Generic Attribute (1801) Service Changed (2a05)	INDICATE			
0014 → 00 0016 0018 001a	Generic Access (1800) Device Name (2a00) Appearance (2a01) 2aa6	READ READ READ	Long name works now Unknown 00		
0028 → ff 002a	4fafc2011fb5459e8fccc5c9c331914b beb5483e36e14688b7f5ea07361b26a8	READ, NOTIFY	Temperature: 24.4°C 0a Humidity: 27.1%		



File Actions Edit View Help

10.0.2.0/24 > 10.0.2.15 » ble.show

RSSI	MAC	Name	Vendor	Flags		Seen
-42 dBm -60 dBm -72 dBm -82 dBm -88 dBm	7c:9e:bd:66:56:8e bf:ba:cd:df:64:a6 7c:30:d1:15:50:9b 02:dc:b8:c9:84:63 e9:7b:8c:51:94:dc	The state of the s	Espressif Inc. Apple, Inc.	BR/EDR Not Supported Limited Discoverable, BR/EDR Not Supported BR/EDR Not Supported	* * * * * * * * * * * * * * * * * * *	20:51:41 20:51:40 20:51:41 20:51:40 20:51:39

```
> 10.0.2.15 » ble.enum 7c:9e:bd:66:56:8e
[20:51:43] [sys.log] [inf] ble.recon connecting to 7c:9e:bd:66:56:8e ...
        24 > 10.0.2.15 » [20:51:47] [ble.device.new] new BLE device detected as 62:11:75:C0:63:D7 -59 dBm.
      0/24 > 10.0.2.15 » ble.enum 7c:9e:bd:66:56:8e
[20:51:54] [sys.log] [inf] ble.recon connecting to 7c:9e:bd:66:56:8e ...
         24 > 10.0.2.15 » [20:51:59] [sys.log] [war] ble.recon connection timeout
           > 10.0.2.15 » ble.enum 7c:9e:bd:66:56:8e
[20:52:02] [sys.log] [inf] ble.recon connecting to 7c:9e:bd:66:56:8e ...
      .0/24 > 10.0.2.15 » [20:52:07] [sys.log] [war] ble.recon connection timeout
           > 10.0.2.15 » ble.enum 7c:9e:bd:66:56:8e
[20:52:08] [sys.log] [inf] ble.recon connecting to 7c:9e:bd:66:56:8e ...
        24 > 10.0.2.15 » [20:52:13] [sys.log] [war] ble.recon connection timeout
    .2.0/24 > 10.0.2.15 » [20:52:18] [ble.device.lost] BLE device E9:7B:8C:51:94:DC (Apple, Inc.) lost.
  0.2.0/24 > 10.0.2.15 » [20:52:18] [ble.device.lost] BLE device 7C:30:D1:15:50:9B lost.
          4 > 10.0.2.15 » [20:52:23] [ble.device.lost] BLE device BLE Server 7C:9E:BD:66:56:8E (Espressif Inc.) lost.
    .2.0/24 > 10.0.2.15 » ble.enum 7c:9e:bd:66:56:8e
   ..2.0/24 > 10.0.2.15 » [20:52:29] [sys.log] [err] BLE device with address 7c:9e:bd:66:56:8e not found.
   0.2.0/24 > 10.0.2.15 » [20:52:29] [ble.device.new] new BLE device detected as E9:7B:8C:51:94:DC (Apple, Inc.) -86 dBm.
      .0/24 > 10.0.2.15 » ble.enum 7c:9e:bd:66:56:8e
      0/24 > 10.0.2.15 » [20:53:18] [sys.log] [err] BLE device with address 7c:9e:bd:66:56:8e not found.
      0/24 > 10.0.2.15 » ble.enum 7c:9e:bd:66:56:8e
[20:53:20] [sys.log] [err] BLE device with address 7c:9e:bd:66:56:8e not found.
         4 > 10.0.2.15 » ble.show
```

RSSI .	MAC	Name	Vendor	Flags	Connect	Seen
-57 dBm -60 dBm -84 dBm -86 dBm	62:11:75:c0:63:d7 bf:ba:cd:df:64:a6 02:dc:b8:c9:84:63 e9:7b:8c:51:94:dc	ST2S NetCamera-DD9B000L3T	Apple, Inc.	Limited Discoverable, BR/EDR Not Supported BR/EDR Not Supported	**	20:53:22 20:53:21 20:53:19 20:52:57



Thanks ...