
a
Single-phase states
n = 489
Observed phases included
481/489 (98.4%)
Exact assemblage
306/489 (62.6%)
b
Tie lines
n = 41
Observed phases included
40/41 (97.6%)
Exact assemblage
40/41 (97.6%)
c
Partial tie lines
n = 164
Observed phases included
78/164 (47.6%)
Exact assemblage
78/164 (47.6%)
d
Three-phase state
n = 1
Observed phases included
0/1 (0.0%)
Exact assemblage
0/1 (0.0%)