



SERVICE REPORT

Tel.: +971 6 741 2778
Fax: +971 6 741 2595
P.O. Box: 7777, Ajman, UAE
e-mail: info@amaanajh.com
Website: www.amaanajh.com

SRN: **46099**

Customer Amaan Test Client LLC		Job No TKT-TEST-001	Page 1 of 1				
		Site Name Marina Tower A	Location Floor 12 / Electrical Room / Panel EP-12				
Engineer / Technician Ahmed Al-Rashid		Date 15 Jul 2026					
Fire Alarm System			Time Arrive	Hrs	09	Mns	15
			Time Left	Hrs	12	Mns	40
Qty 2	Type Addressable		Travel Time	Hrs	00	Mns	45
Make Notifier NFS2-3030	No. of Zones / Loops 4 loops / 12 zones		Total	Hrs	03	Mns	25

Fire Fighting System				Type of Job	
Fire Extinguisher	☒	Gas Suppression	☐	Maintenance	☒
Hose Reel	☒	Kitchen Hood	☐	Installation	☐
Sprinkler	☒	Wet / Dry Riser	☐	Rectification	☐
Fire Pump Set	☒	Others	☐	Others	☐

Comments:	
TEST CONTENTS — Preventive maintenance completed on fire alarm and fire fighting systems.	
1. Inspected Notifier panel; cleared 2 supervisory faults on Loop 2.	
2. Tested smoke detectors on Floor 12 (zones 7–9); all devices responded.	
3. Checked hose reel cabinet pressure and extinguisher tags — OK.	
4. Verified fire pump auto-start on pressure drop simulation.	
Recommendation: Replace aging smoke detector SD-12-04 at next visit.	

Parts Used	Specification	Qty	Parts Required	Specification	Qty
Smoke Detector	Notifier FSP-851 — Loop 2 Zone 8	1	Smoke Detector	Notifier FSP-851	1
Cable 1.5mm ²	Fire-rated red	5	Detector Base	B501	1
Cable Gland	M20 brass	2			

Customer Remarks:	
Work completed satisfactorily. Please schedule follow-up for detector replacement next week.	

Customer Name : Omar Al-Hassan	Engineer/Technician Name: Ahmed Al-Rashid
Mobile No: +971 50 123 4567	ID No: EMP-2048