

Drone Inspection Report

Severity: HIGH

Detections:

tv - 0.3

Defects:

9 possible cracks detected

Alerts:

Crack detected — structural inspection required

Inspection Image:

