

AeroInspect Report

Severity: HIGH

Detections:

crack (0.67)

Defects:

1 cracks detected

Alerts:

Structural crack detected

