

Drone Inspection Report

Severity: HIGH

Detections:

train - 0.29

Defects:

1 possible cracks detected

Alerts:

Crack detected — inspection required

Inspection Image:

