

Release Notes for

AT32F423 Firmware Library Drivers

V2.0.8-2026/06/02

1. PWC
 - `__force_stores()` is replaced with the `__ISB()` and `__DSB()` to adapt to different compilers
2. CRM
 - Updated the processes of the `crm_reset()`, `crm_reset()` and `crm_hick_divider_select()` to avoid potential clock failure during switching
3. EXINT
 - Added a new `crm_hick_divider_select()` to adapt to software trigger without edge configuration requirement
4. Updated some notes

V2.0.7-2025/11/24

5. ADC
 - Removed unnecessary bit name “spt_bit.cspt18” and the register definition “csts_bit”
6. CRM
 - Changed the bit name from `adc14rst` to `tmr14rst`
 - Removed unnecessary `CRM_xxx_PERIPH_LOWPOWER` definitions
7. TMR
 - Updated these functions: `tmr_pwm_input_config()`, `tmr_encoder_mode_config()` and `tmr_output_channel_config()`.
The channel must be disabled before configuring channel mode, otherwise it fails to switch between channel modes
8. Updated some notes

V2.0.6-2025/01/20

1. PWC
 - Updated LDO output level settings, removed LDO configuration option “PWC_LDO_OUTPUT_1V0” and added “PWC_LDO_OUTPUT_1V1”.

V2.0.5-2024/12/13

1. CAN
 - Updated “`can_transmit_cancel()`” function writing to avoid cross-mailbox interference due to misoperation.
2. USB
 - Updated “`usb_hch_halt()`” function in host mode and improved channel halt processing flow.
 - Updated “`usb_hc_enable()`” function in host mode to ensure that its original state is cleared when enabling the corresponding channel.
 - Updated “`usb_host_disable()`” function in host mode, and updated process of

disabling channels to avoid inadvertently opening the remaining channels.

- Updated “usb_ept_open()” function in device mode and added synchronous transfer handling (frame number ignored).
 - Updated “usb_ept_close()” function in device mode, and improved endpoint closing process.
3. Updated some notes.

V2.0.4-2024/08/08

1. Updated some notes.

V2.0.3-2024/01/05

1. Fixed the IAR7.4 compilation warning issue of some drivers.

V2.0.2-2023/10/26

1. Added “interrupt_flag_get()” function to each of the IP sections.
2. Optimized system clock switching process.
3. Updated TMR brake initialization function “tmr_brkdt_config ()”.
4. Updated baud rate calculation in USART initialization function “usart_init()”.
5. Updated IRTMR driver.
6. Updated some notes.

V2.0.1-2023/08/04

1. Added CRC polynomial support.
2. Updated “scfg_mem_map_get()” function.
3. Updated some notes.

V2.0.0-2023/03/24

1. Initial release.