# Release Notes for AT32F425 Firmware Library Drivers

### V2.0.5-2024/12/13

- 1. Updated CAN driver.
- 2. Updated USB driver.
- 3. Updated some notes.

## V2.0.4-2024/08/08

1. Updated some notes.

### V2.0.3-2024/01/05

- 1. Fixed IAR7.4 compilation warning issue of some drivers.
- 2. Updated timer brake filter configuration parameters.

#### V2.0.2-2023/10/26

- 1. Added the function interrupt\_flag\_get to each of the IP sections.
- 2. Updated IRTMR drivers.

### V2.0.1-2023/08/04

- 1. Updated the process of judging "sector" conditions in the *flash\_slib\_enable*.
- 2. Added CRC polynomial support.
- 3. Updated the process of the adc\_ordinary\_channel\_set and adc\_preempt\_channel\_set.
- 4. Updated the scfg\_mem\_map\_get.
- 5. Updated relevant notes.

### V2.0.0-2022/11/18

1. The CRM\_HICK48\_NODIV is considered the default setting when HICK is used as PLL clock source.