# Release Notes for AT32WB415 Firmware Library

# V2.1.2-2024/12/13

- 1. Updated core DSP library.
- 2. Updated CAN driver.
- 3. Updated USB driver.
- 4. Updated I2C eeprom demo and added multi-page write logic.
- 5. Optimized PWR driver and demo.
- 6. Updated some notes.

# V2.1.1-2024/08/08

- 1. Updated USB driver.
- 2. Updated the "i2c\_flag\_clear" and "i2c\_init" functions.
- 3. Updated msc iap demo for better compatibility.
- 4. Updated initialization configuration process of I<sup>2</sup>C DMA related demos.
- 5. Fixed AC6 compilation problems of some demos.
- 6. Updated some notes.

### V2.1.0-2024/02/01

1. Updated slib demo.

# V2.0.9-2024/01/26

- Updated usbd\_core\_type 4-byte alignment.
- 2. Updated USB hid report descriptor.
- 3. Added comparator output parameter definition.
- 4. Updated some notes.

### V2.0.8-2024/01/05

- 1. Updated counter counting mode in input capture demo of timer.
- 2. Fixed HID low-speed identification problem of some USB demos.
- 3. Updated systick initialization function in systick interrupt demo.
- 4. Added winusb demo.
- 5. Updated the method to call the xx interrupt flag get function in all demos.

# V2.0.7-2023/10/26

- 1. Updated USB drivers.
- 2. Updated some notes and readme.

# V2.0.6-2023/08/04

- 1. Added AT32IDE project to demons under utilities.
- Added CRC polynomial support.
- 3. Updated USB driver and demo, improved data alignment and code process.
- Improved redirecting compatibility while using printf in IAR9.
- 5. Added macro definitions regarding Flash size and Flash demo.
- 6. Updated related notes.

### V2.0.5-2023/02/16

- 1. Fixed AC6 compilation problems in freertos demo in *utilities*.
- 2. Added LEXT VALUE macro definition in at32wb415 conf.h.
- Modified the location of crm\_reset in system\_clock\_config function to avoid any error during system clock switch.
- 4. Adjusted the USB set address timing and modified USB host enumeration timeout processing flow.
- 5. Updated some notes.

### V2.0.4-2022/11/18

- 1. Deleted the version and date entries from the header of each file.
- Added Release Notes\_Drivers to record the updates of drivers separately, which is located under libraries\drivers.
- 3. Updated I2C interrupts and changed DMA demo to non-blocking.
- 4. Fixed the problem of USB cdc msc composite failure in linux environment.
- 5. Updated USB virtual msc iap demo for linux environment.
- Updated USB audio related contents for better compatibility.
- 7. Updated IAR Programmer.exe.
- 8. Added interrupt enable determination to the flag bit detection for the interrupt function of USART interrupt demo.
- Added repeat\_conversion\_loop\_transfer demo to ADC to allow DMA to obtain ADC data in a circular way.

### V2.0.3-2022/08/16

- 1. Updated the I<sup>2</sup>C eeprom demo with additional 16-bit address support.
- 2. Added USB host CDC demo.
- 3. Added IAR V9.3 project demo under template.
- 4. Fixed the problem of printf's failure to output in gcc environment.
- 5. Startup file supports configuration wizard.

### V2.0.2-2022/06/28

- 1. Added a demo on how to enable Flash access protection.
- Added IO toggle demo.
- 3. Updated some demos, their drive processes, and some notes.

# V2.0.1-2022/05/20

- 1. Modified descriptors of the USB virtual msc iap demo.
- Added USB composite\_vcp\_msc demo.
- 3. Updated some demos, their drive processes, and some notes.

# V2.0.0-2022/02/11

1. Initial release of AT32WB415 firmware library.